



MUNICIPALITY OF TEMAGAMI

2023 Bridge Inspection Report

Project #23-0658
August 2023

TABLE OF CONTENTS

1. Introduction1
 1.1 Inspection Procedures2
2. Inspection Summaries2
 2.1 Wilson Lake Bridge No. 1.....2
 2.2 Wilson Lake Bridge No. 2.....2
 2.3 Temagami Lake Access Road Bridge3
3. Improvement Costs4
4. Conclusions and Recommendations5

LIST OF FIGURES

Figure 1: Key Map - Bridge Locations 1

LIST OF TABLES

Table 1: Repair Costs 4
Table 2: Maintenance Costs..... 4

APPENDIX A – Glossary of Definitions

APPENDIX B – OSIM Forms

1. INTRODUCTION

TULLOCH Engineering Inc. has been retained by the Municipality of Temagami to undertake detailed visual inspections of the municipally owned bridges within their jurisdiction. In accordance with Ontario Regulation 104/97 – Standards for Bridges, the structural integrity, safety, and condition of every bridge shall be determined through the performance of at least one inspection in every second calendar year under the direction of a professional engineer and in accordance with the Ontario Structure Inspection Manual (OSIM). O. Reg. 472/10, s. 2.

The goal of the structural inspections is to ensure that an acceptable standard is being maintained for each bridge in terms of public safety, comfort, and convenience. The objectives of the inspections are as follows:

- To identify critical maintenance, rehabilitation, and or replacement needs of the bridges
- To protect and prolong the useful life of the bridges
- To provide a basis for scheduling and funding of maintenance, rehabilitation repairs, or replacement of the bridges

This report contains completed OSIM inspection forms, relevant photographs, suggested repairs, and estimated costs for repairs at each site. The bridges inspected as part of this assignment are shown on the key map provided in Figure 1 below.




Figure 1: Key Map - Bridge Locations

1.1 Inspection Procedures

Detailed visual inspections involve a review of each primary structural element. The structural elements are identified by primary groupings and sub-groupings of each element. Material defects such as wood rot or concrete spalling were recorded and measured in the field, refer to Appendix A for a full glossary of terms for the material defects. The condition of each element is quantified and assessed with a rating of 'excellent', 'good', 'fair', or 'poor'. The condition ratings are quantified for either a portion of the total structural element or the entirety of the structural element.

2. INSPECTION SUMMARIES

The results of the detailed visual inspections are recorded using standard Ontario Structure Inspection Manual (OSIM) forms. The forms provide a report of existing data and conditions at the time of the inspection for each bridge. Results of the previous inspections completed in 2021 were used as a template for this round of inspections. Updated OSIM forms are located in Appendix B. The reports identify additional inspections required and recommended work to repair deficiencies along with a schedule for such repairs. The following summarizes the results of our inspections.

2.1 Wilson Lake Bridge No. 1

Wilson Lake Bridge No.1 is located approximately 6.8 km southwest of Highway 11 on Wilson Lake Road. The structure is a triple span of 12.2 m long and 5.9 m wide with steel girders and a timber deck and wearing surface. The last major rehab occurred in 2014, with the installation of new steel pile caps, timber ballast walls, superstructure, and railings. Overall, the structure is in good condition with a BCI of 96 and a BSI of 89. The structure requires minor maintenance and no repairs.

Recommended Maintenance

1 year

- Remove debris from pile caps and deck wearing surface
- Straighten wood offset blocks on the barrier posts
- Remove remnants of beaver dam under structure
- Trim back shoulder vegetation
- Clean deck wearing surface

Recommended Repairs

None

2.2 Wilson Lake Bridge No. 2

Wilson Lake Bridge No.2 is located approximately 12.4 km southwest of Highway 11 on Wilson Lake Road. The structure is a single span 21.3 m long 3.3 m wide Bailey Bridge consisting of 7 Bailey truss bays with a timber deck and wearing surface. The last major rehab occurred in 2011,

with the replacement of all timber bearing cribs, guide rail posts, and the correction of settlement by adding an additional layer of 200x200 mm timber sections to the bearing cribs. Overall, the structure is in poor condition with a BCI of 42 and a BSI of 32. Given the age and condition of the structure, it would be prudent to consider replacing it within the next 1-5 years. The bridge requires several maintenance and repair items completed as listed below.

Recommended Maintenance

1 year

- Monitor movement of the bearing cribs.
- Monitor for further deflection of approach ramps.
- Clean vegetation and debris from bearings, base plates, bailey panels.
- Reset the rotated wood offset blocks on the guide rail posts.
- Replace the curbs on structure wearing surface.
- Trim back the vegetation from the roadway and signage.
- Regrade potholes at approaches.

Recommended Repairs

1 – 5 years

- Replace the missing 200x200 mm timber section in the northeast bearing crib.
- Sandblast structural steel and repaint or replace members.
- Replace the damaged steel beam guide rails.
- Replace severely pitted cross bracing members.
- Replace the timber wearing surface.

2.3 Temagami Lake Access Road Bridge

Lake Temagami Access Road Bridge is located approximately 5 km west of Highway 11 on Lake Temagami Access Road. The structure is a single span 7.3 m long 8.1 m wide steel girder bridge with a fiberglass deck and asphalt wearing surface, constructed in 2010. The last major rehab occurred in 2022, with the replacement of all approaching guide rails, west gabion baskets and correction of the undermining on the west abutment wall. Overall, the structure is in good condition with a BCI of 73 and a BSI of 67, however, there is moderate undermining occurring under the east abutment wall. Given the severity of the undermining the structure requires rehabilitation within the next 1-5 years to continue to function safely.

Recommended Maintenance

1 year

- Clear the remnants of the beaver dam upstream of the structure.
- Remove the gravel from the deck and approaching wearing surface.

Recommended Repairs

1 – 5 years

- Repair the undermining of the east abutment.
- Reinstall gabion baskets after the undermining repairs are completed.

3. IMPROVEMENT COSTS

The tables below summarize the estimated cost of the repair and rehabilitation required for the deficiencies identified through the inspection process. Cost tables have been split into maintenance items and repair item costs.

Table 1: Repair Costs

Repairs	Wilson Lake Bridge No. 1	Wilson Lake Bridge No. 2	Lake Temagami Access Road Bridge	Total Cost (Sum)
Immediate	\$ 0	\$ 0	\$ 0	\$ 0
1-5 years	\$ 0	\$ 256,000	\$ 150,000	\$ 406,000
6-10 years	\$ 0	\$ 0	\$ 0	\$ 0
	Total			\$ 406,000

Table 2: Maintenance Costs

Maintenance	Wilson Lake Bridge No. 1	Wilson Lake Bridge No. 2	Lake Temagami Access Road Bridge	Total Cost (Sum)
Immediate	\$ 0	\$ 0	\$ 0	\$ 0
1 year	\$ 4,000	\$ 5,000	\$ 3,000	\$ 12,000
2 years	\$ 0	\$ 2,000	\$ 0	\$ 2,000
	Total			\$ 14,000

4. CONCLUSIONS AND RECOMMENDATIONS

Upon completion of the biennial structure inspections, a number of recommendations have been identified for both short and long-term planning with municipal structures.

Critical items have been noted above and should be scheduled to be undertaken by the Municipality as soon as possible/practical.

Wilson Lake Bridge No.1 is in good condition and in our opinion does not require any major maintenance or repairs.

Given the age and structural deterioration of the Wilson Lake Bridge No.2, we feel it prudent for the Township to start planning for the replacement of the structure in the next 1-5 years.

Lake Temagami Access Road Bridge has moderate erosion occurring underneath the east abutment wall. It is our recommendation that this be addressed and repaired within one year.

We trust that the contents of this report sufficiently outline the requirements for bridge maintenance, repair, and replacement. Should you have any questions or comments on the contents of this report, please do not hesitate to contact our office.

Respectfully Submitted,

TULLOCH ENGINEERING INC.



Kevin Louch, P. Eng.
Project Engineer



APPENDIX A

Glossary of Definitions

Abutment - A substructure unit which supports the end of the structure and retains the approach fill.

Auxiliary Components - Any component which does not share in the load carrying capacity of the structure.

Biennial Structure Inspection - An inspection performed in every second calendar year to assess the condition of the structure, in accordance with the methodology described in OSIM.

Bridge - A structure which provides a roadway or walkway for the passage of vehicles, pedestrians or cyclists across an obstruction, gap or facility and is greater than or equal to 3 m in span.

Bridge Condition Index (BCI) - The BCI rating is a planning tool developed by the Ontario Ministry of Transportation that helps schedule maintenance and rehabilitation work. The BCI is not used to rate or indicate the safety of a bridge. The BCI result is organized into ranges from 0 to 100. To calculate the BCI rating, the current dollar value of the bridge is divided by the replacement cost of the bridge. The replacement value is based on the cost to reconstruct a new bridge. Using this formula enables the Owner to make an informed decision about the amount of work a bridge requires and whether or not to pursue replacement over repair in the near future.

Rating	Maintenance Schedule
Good: BCI Range 70 -100	Maintenance is not usually required within the next five years
Fair: BCI Range 60 -70	Maintenance work is usually scheduled within the next five years. This is the ideal time to schedule major bridge repairs to get the most out of bridge spending.
Poor: BCI Less than 60	Maintenance work is usually scheduled within one year.

Bridge Sufficiency Index (BSI) – The BSI rating is a planning tool developed by the Ontario Ministry of Transportation. The BSI is calculated using the BCI rating less ratings for Importance Factors including Traffic, Economic Implications, Bridge Width and Bridge Profile or Alignment. It is a planning tool with a range of 0 to 100 and helps prioritize maintenance and rehabilitation work, and replacement, with bridges of equal BCI but lower BSI having importance over bridges with higher BSI.

Chord - The upper and lower main longitudinal component in trusses or arches extending the full length of the structure.

Coating - The generic term for paint, lacquer, enamel, sealers, galvanizing, metallizing, etc.

Concrete Deck Condition Survey - A detailed inspection of a concrete deck in accordance with The Structure Rehabilitation Manual.

Culvert (Structural) - A Structure that forms an opening through soil and has a span of 3 metres or more

Defect - An identifiable, unwanted condition that was not part of the original intent of design.

- **Scaling** - Scaling is the local flaking, or loss of the surface portion of concrete or mortar as a result of the freeze-thaw deterioration of concrete. Scaling is common in non-air-entrained concrete but can also occur in air-entrained concrete in the fully saturated condition. Scaling is prone to occur in poorly finished or overworked concrete where too many fines and not enough entrained air is found near the surface.
- **Disintegration** - Disintegration is the physical deterioration or breaking down of the concrete into small fragments or particles. The deterioration usually starts in the form of scaling and, if allowed to progress beyond the level of very severe scaling is considered as disintegration. Disintegration may be caused by de-icing chemicals, sulphates, chlorides or by frost action.
- **Erosion** - Erosion is the deterioration of concrete brought about by water-borne sand and gravel particles scrubbing against concrete surfaces. Similar, damage may be caused by flowing ice. Erosion is sometimes combined with the chemical action of air and water-borne pollutants which accelerate the breakdown of the concrete. Erosion is generally an indication that the concrete is not durable enough for the environment in which it has been placed.
- **Corrosion of Reinforcement** - Corrosion is the deterioration of reinforcement by electrolysis. The alkali content in concrete protects the reinforcement from corrosion. However, when chloride ions above a certain concentration are dissolved in water and penetrate through the concrete to the reinforcement this protection breaks down and corrosion starts. In the initial stages, corrosion may appear as a rust-stain on the concrete surface. In the advanced stages, the surface concrete above the reinforcement cracks, delaminates and spalls off exposing heavily rusted reinforcement.
- **Delamination** - Delamination is defined as a discontinuity of the surface concrete which is substantially separated but not completely detached from concrete below or above it. Visibly, it may appear as a solid surface but can be identified as a hollow sound by tapping or chain dragging. Delamination begins with the corrosion of reinforcement and subsequent cracking of the concrete. Delamination or debonding may also occur in concrete that has been patched or overlaid due to the continued deterioration of the older concrete. This may happen even in the absence of any rusting of reinforcing steel.
- **Spalling** - A spall is a fragment, which has been detached from a larger concrete mass. Spalling is a continuation of the delamination process whereby the actions of external loads, pressure exerted by the corrosion of reinforcement or by the formation of ice in the delaminated area results in the breaking off of the delaminated concrete.

- Cracking - A crack is a linear fracture in concrete which extends partly or completely through the member. Cracks in concrete occur as a result of tensile stresses introduced in the concrete. Tensile stresses are initially carried by the concrete and reinforcement until the level of the tensile stresses exceeds the tensile capacity of the concrete. After this point the concrete cracks and the tensile force is transferred completely to the steel reinforcement. The crack widths and distribution is controlled by the reinforcement in reinforced and prestressed concrete, whereas in plain concrete there is no such control.
- Alkali-Aggregate Reaction - In Ontario, there exists several sources of aggregates that react adversely with the alkalis in cement to produce a highly expansive gel. Currently, these sources of reactive aggregates are generally avoided, but they do exist in many existing structures and still may occur in newer structures. The two general types of reactions in Ontario are alkali-carbonate and alkali-silica reaction. The expansion of the gel and aggregates occurs due to hydroxyl ions in the concrete pore solution, which under moist conditions, leads to cracking and deterioration of the concrete.
- Surface Defects - Surface defects are not necessarily serious in themselves; however, they are indicative of a potential weakness in the concrete, and their presence should be noted but not classified as to severity, except for honeycombing and pop-outs.
 - STRATIFICATION is the separation of the concrete components into horizontal layers in over-wetted or over-vibrated concrete. Water, laitance, mortar and coarse aggregates occupy successively lower positions. A layered structure in concrete will also result from the placing of successive batches that differ in appearance.
 - SEGREGATION is the differential concentration of the components of mixed concrete resulting in nonuniform proportions in the mass. Segregation is caused by concrete falling from a height, with the coarse aggregates settling to the bottom and the fines on top. Another form of segregation occurs where reinforcing bars prevent the uniform flow of concrete between them.
 - COLD JOINTS are produced if there is a delay between the placement of successive pours of concrete, and if an incomplete bond develops at the joint due to the partial setting of the concrete in the first pour.
 - DEPOSITS are often left behind where water percolates through the concrete and dissolves or leaches chemicals from it and deposits them on the surface.
 - HONEYCOMBING is produced due to the improper or incomplete vibration of the concrete which results in voids being left in the concrete where the mortar failed to completely fill the spaces between the coarse aggregate particles.
 - POP-OUTS are shallow, typically conical depressions, resulting from the breaking away of small portions of the concrete surface, due to the expansion of some aggregates or due to frost action. The shattered aggregate particle may be found at the bottom of the depression, with a part of the aggregate still adhering to the pop-out cone.
 - ABRASION is the deterioration of concrete brought about by vehicles or snow-plough blades scraping against concrete surfaces, such as, decks, curbs, barrier walls or piers.

- WEAR is usually the result of dynamic and/or frictional forces generated by vehicular traffic, coupled with the abrasive influx of sand, dirt, and debris. It can also result from the friction of ice or water-borne particles against partly or completely submerged members. The surface of the concrete appears polished.
- SLIPPERY CONCRETE SURFACES may result from the polishing of the concrete deck surface by the action of repetitive vehicular traffic.

Detailed Visual Inspection - An element by element visual assessment of material defects, performance deficiencies and maintenance needs of a structure.

Deterioration - A defect that has occurred over a period of time.

Distress - A defect produced by loading.

Elements - The individual parts of a structure defined for inspection purposes. Several bridge components may be grouped together to form one bridge element for inspection purposes

Environment - An element's exposure to salt spray:

- Benign - Not exposed (e.g. River Pier)
- Moderate - Exposed but element protected (e.g. Asphalt covered and waterproofed deck)
- Severe - Exposed and element not protected (e.g. Exposed concrete deck, Barrier Wall)

Evaluation - The determination of the load carrying capacity of structures in accordance with the requirements of the Canadian Highway Bridge Design Code.

Maintenance - Any action which is aimed at preventing the development of defects or preventing deterioration of a structure or its components.

Primary Components - The main load carrying components of the structure.

Rehabilitation - Any modification, alteration, retrofitting or improvement to a structure subsystem or to the structure which is aimed at correcting existing defects or deficiencies.

Remaining Service Life - Remaining Service Life is an estimate of the useful remaining life of the structure and is based on the year of construction or major rehabilitation and a service life of 50 years for culverts that are not plastic, polymer coated or concrete, 50 years for bridges constructed prior to 2000, 50 years for steel bridges and 70 years for other structures.

Repair - Any modification, alteration, retrofitting or improvement to a component of the structure which is aimed at correcting existing defects or deficiencies.

Retaining Wall - Any structure that holds back fill and is not connected to a bridge.

Secondary Components - Any component which helps to distribute loads to primary components, or carries wind loads, or stabilizes primary components.

Sign Support - A metal, concrete, or timber structure, including supporting brackets, service walks and mechanical devices where present, which support a luminaire, sign or traffic signal and which span or extend over a highway.

Span - The horizontal distance between adjacent supports of the superstructure of a bridge, or the longest horizontal dimension of the cross-section of a culvert or tunnel taken perpendicular to the walls.

Stringers - Stringers span between floor beams and provide the support for the deck above.

Structure - Bridge, culvert, tunnel, retaining wall or sign support.

Suspected Performance Deficiency - A Suspected Performance Deficiency should be recorded during an inspection, if an element's ability to perform its intended function is in question, and one or more performance defects exist.

APPENDIX B

OSIM Forms

Inventory Data:

Structure Name	<input type="text" value="Wilson Lake Road Bridge 1"/>		
Main Highway #	<input type="text"/>	On <input checked="" type="checkbox"/> or Under <input type="checkbox"/> Structure	Service on structure: <input type="checkbox"/> Navig. Water <input type="checkbox"/> Non-Navig. Water <input type="checkbox"/> Rail <input checked="" type="checkbox"/> Road <input type="checkbox"/> Ped. <input type="checkbox"/> Other
Location description	<input type="text" value="6.8 km Southwest of Hwy 11"/>	Service under	<input type="checkbox"/> Navig. Water <input checked="" type="checkbox"/> Non-Navig. Water <input type="checkbox"/> Rail <input type="checkbox"/> Road <input type="checkbox"/> Ped. <input type="checkbox"/> Other
Owner/Custodian	<input type="text" value="Municipality of Temagami"/>	LHRS:	<input type="text"/> LHRS offset: <input type="text"/>
MTO Region	<input type="text" value="Northern"/>	Latitude:	<input n"="" type="text" value="46° 55' 28"/> Longitude: <input type="text" value="79° 48' 35" w"=""/>
Regional Engineer	<input type="text"/>	Heritage Designation:	<input checked="" type="checkbox"/> Not Cons. <input type="checkbox"/> Cons./not App. <input type="checkbox"/> List/not Desig. <input type="checkbox"/> Desig./not List <input type="checkbox"/> Desig. & List
MTO Area	<input type="text" value="Sudbury"/>	Hwy Class:	Freeway <input type="checkbox"/> Arterial <input type="checkbox"/> Collector <input type="checkbox"/> Local <input checked="" type="checkbox"/>
Old County	<input type="text"/>	Posted Speed	<input type="text"/> No. of Lanes <input type="text" value="2"/>
Township	<input type="text" value="Temagami"/>	AADT	<input type="text"/> % Truck <input type="text"/>
Structure Type 1	<input type="text" value="Girder"/>	Travel Stream	<input type="text" value="E"/>
Structure Material 1	<input type="text" value="Steel"/>	Traffic Directional Bound	<input type="text" value="S-N"/>
Structure Type 2	<input type="text" value="Deck"/>	Inspection Route Sequence	<input type="text"/>
Structure Material 2	<input type="text" value="Timber"/>	Inspection Frequency	<input type="text" value="2"/> (years)
Total Deck Length	<input type="text" value="12.2"/> (m)	Inspection Year	<input type="text" value="2023"/>
Overall Str. Width	<input type="text" value="5.9"/> (m)	Inspection Duration	<input type="text"/> (hrs)
Culvert length	<input type="text"/> (m)	Interchange Number	<input type="text"/>
Total Deck Area	<input type="text" value="72.0"/> (sq.m)	Interchange Structure Number	<input type="text"/>
Roadway Width	<input type="text" value="5.2"/> (m)	Min. Vertical Clearance	<input type="text"/> (m)
Skew Angle	<input type="text" value="0"/> (Degree)	Detour Distance	<input type="text"/> (km)
No. of Spans	<input type="text" value="3"/>	Fill on Structure	<input type="text"/> (m)
Span Lengths	<input type="text" value="North 3.9; 4.2; 3.9 South"/> (m)		
<u>For retaining wall:</u>			
Total Wall Length	<input type="text"/> (m)	Max. Wall Height	<input type="text"/> (m)
Total Wall Area	<input type="text"/> (sq.m)	Ave. Wall Height	<input type="text"/> (m)
		Angle of Backfill	<input type="text"/> (Degree)

Rev 2018

Rev 2018

Rev 2018

Historical Data:			
Year Built	<input type="text"/>	Year of superstruct. constructed	<input type="text"/>
Last Reg OSIM Inspection	<input type="text" value="2021"/>	Year of Last Minor Rehab.	<input type="text"/>
Last Enh. OSIM Inspection	<input type="text"/>	Year of Last Major Rehab.	<input type="text" value="Aug 2014"/>
	<input type="text"/>	Current Load Limit	<input type="text"/> (tonnes)
Work History: (Date/description) 2014: New steel pile caps, timber ballast walls. Entirely new superstructure and railing.			
Investigation History: (Date/description)			

Scheduled Improvements:	
Regional Priority Number <input type="text"/>	Programmed Work Year <input type="text"/>
Nature of Program Work: None	

Appraisal Indices:		Comments
Fatigue	None	
Seismic	None	
Scour	None	
Flood	None	
Barrier	None	
Curb	None	
Load Capacity	None	

Rev2008
2018

Field Inspection Information:			
Date of Inspection:	June 20, 2023	Type of Inspection:	<input checked="" type="checkbox"/> Reg. OSIM <input type="checkbox"/> Enh. OSIM
Inspected By:	Kevin Louch, P.Eng.		
Others in Party:	Kaitlyn Hunt		
Enh. Access Equipment:	Measuring Tape, Camera, Hammer		
Special Access Equipment:			
Weather:	Sunny	Temperature:	26°C

2008

Additional Investigations Required:	Priority		
	None	Normal	Urgent
Material Condition Survey	✓		
Detailed Deck Condition Survey:	✓		
Non-destructive Delamination Survey of Asphalt-Covered Deck:	✓		
Concrete Substructure Condition Survey:	✓		
Detailed Coating Condition Survey:	✓		
Detailed Timber Investigation	✓		
Post-Tensioned Strand Investigation	✓		
Underwater Investigation:	✓		
Fatigue Investigation:	✓		
Seismic Investigation:	✓		
Structure Evaluation:	✓		
Monitoring	✓		
Deformations, Settlements and Movements:	✓		
Crack Widths:	✓		
RSS Horizontal movements of face:	✓		
RSS Vertical movements of overall structure:	✓		
RSS Local movements or deterioration of facing elements:	✓		
RSS Horizontal movements within overall structure:	✓		
RSS Vertical movements within overall structure:	✓		
RSS Lateral earth pressure at the back of facing elements:	✓		
Investigation Notes: No further investigation required.			

2018

Overall Structure Notes:	Overall Bridge Condition: BCI 96
Recommended Work on Structure:	<input checked="" type="checkbox"/> None <input type="checkbox"/> Minor Rehab. <input type="checkbox"/> Major Rehab. <input type="checkbox"/> Replace
Timing of Recommended Work:	<input type="checkbox"/> 1 to 5 years <input type="checkbox"/> 6 to 10 years
Overall Comments:	No work needed, only maintenance on wearing surface and stream. Overall in good condition.
Date of Next Inspection:	2025

Rev

Suspected Performance Deficiencies

- | | | |
|---|--|--|
| <p>01 Load carrying capacity</p> <p>02 Excessive deformations (deflections & rotations)</p> <p>03 Continuing settlement</p> <p>04 Continuing movements</p> <p>05 Seized bearings</p> | <p>06 Bearing not uniformly loaded/unstable</p> <p>07 Jammed expansion joint</p> <p>08 Pedestrian/vehicular hazard</p> <p>09 Rough riding surface</p> <p>10 Surface ponding</p> <p>11 Deck/Wall drainage</p> | <p>12 Slippery surfaces</p> <p>13 Flooding/channel blockage</p> <p>14 Undermining of foundation</p> <p>15 Unstable embankments</p> <p>16 Other performance deficiencies</p> |
|---|--|--|

Maintenance Needs

- | | | |
|--|---|---|
| <p>01 N/A</p> <p>02 Bridge Cleaning</p> <p>03 Railing System Repair</p> <p>04 N/A</p> <p>05 Bridge Deck Joint Repair</p> <p>06 N/A</p> | <p>07 Structural Steel Repair</p> <p>08 Concrete Repair</p> <p>09 Timber Repair</p> <p>10 Works for Modular bridges</p> <p>11 Animal/Pest Control</p> <p>12 Bridge Surface Repair</p> | <p>13 Erosion Control at Bridges</p> <p>14 Concrete Sealing</p> <p>15 N/A</p> <p>16 Works for Drainage System</p> <p>17 Sealing (Loose Concrete or ACR Steel)</p> <p>18 Other Maintenance</p> |
|--|---|---|

2018

Rev
2008

Municipal Structure Inspection Form
Wilson Lake Road Bridge 1

MTO Site Number:

Repair and Rehabilitation Required:		Priority			Estimated Construction Cost
Element	Repair and Rehabilitation Required	6 to 10 years	1 to 5 years	Urgent	
Total Cost					\$0

Associated Work:	Comments	Estimated Cost
Other:	Engineering (15%)	\$0
Contingencies:	Contingency (10%)	\$0
Total Cost		\$0

Total Repair and Rehabilitation Cost	\$0
---	------------

Replacement Cost	\$0
-------------------------	------------

Maintenance Required		Priority			Estimated Construction Cost
Element	Repair and Rehabilitation Required	2 year	Within 1 year	Urgent	
Streams	Remove daming under bridge		x		\$1,000
Deck WS	Remove gravel and sand from top		x		\$1,000
Abutment Pile Caps	Remove debris from top of cap		x		\$500
Barrier Post	Straighten offset block		x		\$500
Approach WS	Trim back vegetation		x		\$1,000
Total Maintenance Cost					\$4,000

Justification:

Section View: Facing South



Elevation View: Facing North



Comments:

Element Data

Element Group:	Abutments	Length:	0.25	(m)		
Element Name:	Pile Cap	Width:	5.94	(m)		
Location:	North and South Abutments	Height:	0.25	(m)		
Material:	Steel	Count:	2	each		
Element Type:	W 250x73	Total Quantity:	11.9	(m ²)		
Environment:	<u>Benign</u> / Moderate / Severe	Limited Insp'n:	<input type="checkbox"/>			
Protection System:	Steel Coating					
Condition	Units	Exc.	Good	Fair	Poor	Performance Deficiencies
Data:	<u>m²</u> m / each / % / all	11.9				None

Comments: Light corrosion and flaking of steel coating. Light debris on top of pile cap steel beams.

Performance Deficiencies:

Recommended Work:	<input type="checkbox"/> Minor Rehab	<input type="checkbox"/> Major Rehab	Maintenance Needs:	
	<input type="checkbox"/> Replace	<input checked="" type="checkbox"/> None	<input type="checkbox"/> Urgent	<input checked="" type="checkbox"/> 1 Year <input type="checkbox"/> 2 Year
Timeframe:	<input type="checkbox"/> Urgent	<input type="checkbox"/> 1 - 5 Years	<input type="checkbox"/> 6 - 10 Years	Remove debris from pile caps.
Comments:				

Element Photos



Comments:

Element Data

Element Group:	Abutments	Length:	0.3	(m)		
Element Name:	Pile Bents	Width:	0.3	(m)		
Location:	North and South Abutments	Height:	0.4	(m)		
Material:	Wood	Count:	10	each		
Element Type:	Timber Piles	Total Quantity:	3.8	(m ²)		
Environment:	Benign Moderate Severe	Limited Insp'n:	<input checked="" type="checkbox"/>			
Protection System:	Creoste					
Condition	Units	Exc.	Good	Fair	Poor	Performance Deficiencies
Data:	m ² m / each / % / all		3	0.8		None

Comments: Crack in south abutment diagonal brace.

Performance Deficiencies:

Recommended Work:	<input type="checkbox"/> Minor Rehab	<input type="checkbox"/> Major Rehab	Maintenance Needs:		
	<input type="checkbox"/> Replace	<input checked="" type="checkbox"/> None	<input type="checkbox"/> Urgent	<input type="checkbox"/> 1 Year	<input type="checkbox"/> 2 Year
Timeframe:	<input type="checkbox"/> Urgent	<input type="checkbox"/> 1 - 5 Years	<input type="checkbox"/> 6 - 10 Years		
Comments:					

Element Photos



Comments:

Municipal Structure Inspection Form
Wilson Lake Road Bridge 1

MTO Site Number:

Element Data

Element Group:	Abutments	Length:	n/a	(m)		
Element Name:	Ballast Walls	Width:	7.14	(m)		
Location:	North and South Abutments	Height:	0.84	(m)		
Material:	Wood	Count:	2	each		
Element Type:	Dimension Lumber	Total Quantity:	12.0	(m ²)		
Environment:	Benign / Moderate / Severe	Limited Insp'n:	<input checked="" type="checkbox"/>			
Protection System:	Treated					
Condition	Units	Exc.	Good	Fair	Poor	Performance Deficiencies
Data:	m ² / m / each / % / all	12				

Comments: Minor splits in timber ballast wall.

Performance Deficiencies:

Recommended Work:	<input type="checkbox"/> Minor Rehab	<input type="checkbox"/> Major Rehab	Maintenance Needs:	
	<input type="checkbox"/> Replace	<input checked="" type="checkbox"/> None	<input type="checkbox"/> Urgent	<input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Year
Timeframe:	<input type="checkbox"/> Urgent	<input type="checkbox"/> 1 - 5 Years	<input type="checkbox"/> 6 - 10 Years	
Comments:				

Element Photos

Comments:

Municipal Structure Inspection Form
Wilson Lake Road Bridge 1

MTO Site Number:

Element Data

Element Group:	Piers	Length:	0.25	(m)		
Element Name:	Pile Caps	Width:	5.94	(m)		
Location:	North and South Piers	Height:	0.25	(m)		
Material:	Steel	Count:	2	each		
Element Type:	W 250x73	Total Quantity:	11.9	(m ²)		
Environment:	Benign / Moderate / Severe	Limited Insp'n:	<input type="checkbox"/>			
Protection System:	Steel Coating			Performance Deficiencies		
Condition Data:	Units	Exc.	Good		Fair	Poor
	m ² m / each / % / all	11.5	0.4			None

Comments: Light corrosion and flaking of steel coating.

Performance Deficiencies:

Recommended Work:	<input type="checkbox"/> Minor Rehab	<input type="checkbox"/> Major Rehab	Maintenance Needs:	
	<input type="checkbox"/> Replace	<input checked="" type="checkbox"/> None	<input type="checkbox"/> Urgent	<input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Year
Timeframe:	<input type="checkbox"/> Urgent	<input type="checkbox"/> 1 - 5 Years	<input type="checkbox"/> 6 - 10 Years	
Comments:				

Element Photos



Comments:

Municipal Structure Inspection Form
Wilson Lake Road Bridge 1

MTO Site Number:

Element Data

Element Group:	Piers	Length:	0.3	(m)
Element Name:	Pile Bents	Width:	0.3	(m)
Location:	North and South Piers	Height:	1.3	(m)
Material:	Wood	Count:	10	each
Element Type:	Timber Pile	Total Quantity:	12.3	(m ²)
Environment:	<u>Benign</u> / Moderate / Severe	Limited Insp'n:	<input checked="" type="checkbox"/>	
Protection System:	Creosote			Performance Deficiencies
Condition Data:	Units m ² m / each / % / all	Exc.	Good 11.3	
Poor				
None				
Comments:				
Performance Deficiencies:				
Recommended Work:	<input type="checkbox"/> Minor Rehab	<input type="checkbox"/> Major Rehab	Maintenance Needs:	
	<input type="checkbox"/> Replace	<input checked="" type="checkbox"/> None	<input type="checkbox"/> Urgent	<input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Year
Timeframe:	<input type="checkbox"/> Urgent	<input type="checkbox"/> 1 - 5 Years	<input type="checkbox"/> 6 - 10 Years	
Comments:				
Element Photos				
Comments:				

Municipal Structure Inspection Form
Wilson Lake Road Bridge 1

MTO Site Number:

Element Data

Element Group:	Main Longitudinal Elements	Length:	4	(m) total of both ends
Element Name:	Girders	Width:	0.177	(m)
Location:	Ends	Height:	0.403	(m)
Material:	Steel	Count:	5	each
Element Type:	W 410x54	Total Quantity:	26.7	(m ²)
Environment:	Benign Moderate Severe	Limited Insp'n:	<input type="checkbox"/>	
Protection System:	Steel Coating			Performance Deficiencies
Condition Data:	Units m ² / m / each / % / all	Exc. 26	Good 0.7	
Comments: Light corrosion and flaking of steel coating.				
Performance Deficiencies:				
Recommended Work:	<input type="checkbox"/> Minor Rehab	<input type="checkbox"/> Major Rehab	Maintenance Needs:	
	<input type="checkbox"/> Replace	<input checked="" type="checkbox"/> None	<input type="checkbox"/> Urgent	<input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Year
Timeframe:	<input type="checkbox"/> Urgent	<input type="checkbox"/> 1 - 5 Years	<input type="checkbox"/> 6 - 10 Years	
Comments:				
Element Photos				
Comments:				

Municipal Structure Inspection Form
Wilson Lake Road Bridge 1

MTO Site Number:

Element Data

Element Group:	Main Longitudinal Elements	Length:	8.22	(m)	
Element Name:	Girders	Width:	0.177	(m)	
Location:	Middle	Height:	0.403	(m)	
Material:	Steel	Count:	5	each	
Element Type:	W 410x54	Total Quantity:	55.0	(m ²)	
Environment:	<u>Benign</u> / Moderate / Severe	Limited Insp'n:	<input type="checkbox"/>		
Protection System:	Steel Coating			Performance Deficiencies	
Condition Data:	Units: <u>m²</u> / m / each / % / all	Exc.:	Good:		Fair:
		54.5	0.5		
Comments: Light corrosion and flaking of steel coating.					
Performance Deficiencies:					
Recommended Work:	<input type="checkbox"/> Minor Rehab	<input type="checkbox"/> Major Rehab	Maintenance Needs:		
	<input type="checkbox"/> Replace	<input checked="" type="checkbox"/> None	<input type="checkbox"/> Urgent	<input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Year	
Timeframe:	<input type="checkbox"/> Urgent	<input type="checkbox"/> 1 - 5 Years	<input type="checkbox"/> 6 - 10 Years		
Comments:					
Element Photos					
Comments:					

Municipal Structure Inspection Form
Wilson Lake Road Bridge 1

MTO Site Number:

Element Data

Element Group:	Main Longitudinal Elements	Length:	1.22	(m)		
Element Name:	Diaphragm	Width:	0.065	(m)		
Location:	End (at abutments)	Height:	0.254	(m)		
Material:	Steel	Count:	4	each side		
Element Type:	C 250x23	Total Quantity:	8	each		
Environment:	Benign Moderate Severe	Limited Insp'n:	<input type="checkbox"/>			
Protection System:	Steel Coating			Performance Deficiencies		
Condition	Units	Exc.	Good		Fair	Poor
Data:	m ² / m each / % / all	8				None
Comments: Light corrosion and flaking of steel coating.						
Performance Deficiencies:						
Recommended Work:	<input type="checkbox"/> Minor Rehab	<input type="checkbox"/> Major Rehab	Maintenance Needs:			
	<input type="checkbox"/> Replace	<input checked="" type="checkbox"/> None	<input type="checkbox"/> Urgent	<input type="checkbox"/> 1 Year	<input type="checkbox"/> 2 Year	
Timeframe:	<input type="checkbox"/> Urgent	<input type="checkbox"/> 1 - 5 Years	<input type="checkbox"/> 6 - 10 Years			
Comments:						
Element Photos						
Comments:						

Element Data

Element Group:	Main Longitudinal Elements	Length:	1.22	(m)		
Element Name:	Diaphragm	Width:	0.065	(m)		
Location:	Intermediate (at piers)	Height:	0.254	(m)		
Material:	Steel	Count:	4	each side		
Element Type:	C 250x23	Total Quantity:	8	each		
Environment:	Benign / Moderate / Severe	Limited Insp'n:	<input type="checkbox"/>			
Protection System:	Steel Coating					
Condition	Units	Exc.	Good	Fair	Poor	Performance Deficiencies
Data:	m ² / m / each / % / all	8				

Comments: Light corrosion and flaking of steel coating.

Performance Deficiencies:

Recommended Work:	<input type="checkbox"/> Minor Rehab	<input type="checkbox"/> Major Rehab	Maintenance Needs:
	<input type="checkbox"/> Replace	<input checked="" type="checkbox"/> None	
Timeframe:	<input type="checkbox"/> Urgent	<input type="checkbox"/> 1 - 5 Years	<input type="checkbox"/> 6 - 10 Years
Comments:			

Element Photos



Comments:

Municipal Structure Inspection Form
Wilson Lake Road Bridge 1

MTO Site Number:

Element Data

Element Group:	Coating	Length:	n/a	(m)	
Element Name:	Structural Steel	Width:	n/a	(m)	
Location:	Ends	Height:	n/a	(m)	
Material:	Epoxy Paint	Count:	n/a	each	
Element Type:	Epoxy-Zinc Epoxy-Polyurethane	Total Quantity:	32.9	(m ²)including diaphragm	
Environment:	Benign <u>Moderate</u> Severe	Limited Insp'n:	<input type="checkbox"/>		
Protection System:	Steel Coating			Performance Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor
	m ² / m / each / % / all	22.9	10		

Comments: Light flaking of coating throughout.

Performance Deficiencies:		
Recommended Work:	<input type="checkbox"/> Minor Rehab <input type="checkbox"/> Major Rehab <input type="checkbox"/> Replace <input checked="" type="checkbox"/> None	Maintenance Needs:
Timeframe:	<input type="checkbox"/> Urgent <input type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years	<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Year
Comments:		

Element Photos

Comments:

Municipal Structure Inspection Form
Wilson Lake Road Bridge 1

MTO Site Number:

Element Data

Element Group:	Coating	Length:	n/a	(m)	
Element Name:	Structural Steel	Width:	n/a	(m)	
Location:	Middle	Height:	n/a	(m)	
Material:	Epoxy Paint	Count:	n/a	each	
Element Type:	Epoxy -Zinc Epoxy Ployurethane	Total Quantity:	61.2	(m ²)	
Environment:	<u>Benign</u> / Moderate / Severe	Limited Insp'n:	<input checked="" type="checkbox"/>		
Protection System:	Steel Coating			Performance Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor
	m ² / m / each / % / all	55.7	5.5		
Comments: Light flaking of coating throughout.					
Performance Deficiencies:					
Recommended Work:	<input type="checkbox"/> Minor Rehab	<input type="checkbox"/> Major Rehab		Maintenance Needs:	
	<input type="checkbox"/> Replace	<input checked="" type="checkbox"/> None			
Timeframe:	<input type="checkbox"/> Urgent	<input type="checkbox"/> 1 - 5 Years	<input type="checkbox"/> Urgent		
Comments:			<input type="checkbox"/> 1 Year		
		<input type="checkbox"/> 2 Year			
Element Photos					
Comments:					

Element Data

Element Group:	Decks	Length:	12.22	(m)		
Element Name:	Deck Top	Width:	5.5	(m)		
Location:	-	Height:	0.19	(m)		
Material:	Wood	Count:	n/a	each		
Element Type:	Dimension Lumber	Total Quantity:	67.21	(m ²)		
Environment:	Benign Moderate Severe	Limited Insp'n:	<input checked="" type="checkbox"/>			
Protection System:	Wood Preservative Treatment					
Condition	Units	Exc.	Good	Fair	Poor	Performance Deficiencies
Data:	m ² / m / each / % / all	65	2.21			None
Comments: Hidden under deck wearing surface. Appears to be in good condition based on board ends and soffit. Light twisting and checking in board ends.						
Performance Deficiencies:						
Recommended Work:	<input type="checkbox"/> Minor Rehab <input type="checkbox"/> Replace		<input type="checkbox"/> Major Rehab <input checked="" type="checkbox"/> None		Maintenance Needs: <input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Year	
Timeframe:	<input type="checkbox"/> Urgent <input type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years					
Comments:						

Element Photos



Comments:

Municipal Structure Inspection Form
Wilson Lake Road Bridge 1

MTO Site Number:

Element Data

Element Group:	Decks	Length:	12.22	(m)		
Element Name:	Soffit	Width:	5.0	(m)		
Location:	-	Height:	n/a	(m)		
Material:	Wood	Count:	n/a	each		
Element Type:	Dimension Lumber	Total Quantity:	61.1	(m ²)		
Environment:	<u>Benign</u> / Moderate / Severe	Limited Insp'n:	<input type="checkbox"/>			
Protection System:	Wood Preservative Treatment					
Condition	Units	Exc.	Good	Fair	Poor	Performance Deficiencies
Data:	<u>m²</u> / m / each / % / all	59.6	1.5			
Comments: Moisture stains throughout.						
Performance Deficiencies:						
Recommended Work:	<input type="checkbox"/> Minor Rehab		<input type="checkbox"/> Major Rehab		Maintenance Needs:	
	<input type="checkbox"/> Replace		<input checked="" type="checkbox"/> None			
Timeframe:	<input type="checkbox"/> Urgent		<input type="checkbox"/> 1 - 5 Years		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Year	
Comments:						

Element Photos



Comments:

Municipal Structure Inspection Form
Wilson Lake Road Bridge 1

MTO Site Number:

Element Data

Element Group:	Deck	Length:	12.22	(m)		
Element Name:	Wearing Surface	Width:	4.9	(m)		
Location:	-	Height:	n/a	(m)		
Material:	Wood	Count:	n/a	each		
Element Type:	Dimension Wood	Total Quantity:	59.9	(m ²)		
Environment:	Benign / Moderate / Severe	Limited Insp'n:	<input type="checkbox"/>			
Protection System:	-					
Condition	Units	Exc.	Good	Fair	Poor	Performance Deficiencies
Data:	m ² / m / each / % / all	50	9.9			

Comments: Covered in sand and gravel. Light wear in timber running boards.

Performance Deficiencies:

Recommended Work:	<input type="checkbox"/> Minor Rehab	<input type="checkbox"/> Major Rehab	Maintenance Needs:
	<input type="checkbox"/> Replace	<input checked="" type="checkbox"/> None	
Timeframe:	<input type="checkbox"/> Urgent	<input type="checkbox"/> 1 - 5 Years	<input type="checkbox"/> 6 - 10 Years
Comments:	Remove gravel and sand from wearing surface.		

Element Photos



Comments:

Municipal Structure Inspection Form
Wilson Lake Road Bridge 1

MTO Site Number:

Element Data

Element Group:	Sidewalks/Curbs	Length:	12.22	(m)		
Element Name:	Curbs	Width:	0.14	(m)		
Location:	East and West sides	Height:	0.14	(m)		
Material:	Wood	Count:	2	each		
Element Type:	Dimension Lumber	Total Quantity:	6.84	(m ²)		
Environment:	Benign / Moderate / Severe	Limited Insp'n:	<input type="checkbox"/>			
Protection System:	Wood Preservative Treatment			Performance Deficiencies		
Condition Data:	Units	Exc.	Good		Fair	Poor
	m ² / m / each / % / all	6	0.84			None

Comments: Light weather checks. Wide splits in the top of curbs.

Performance Deficiencies:

Recommended Work:	<input type="checkbox"/> Minor Rehab	<input type="checkbox"/> Major Rehab	Maintenance Needs:
	<input type="checkbox"/> Replace	<input checked="" type="checkbox"/> None	
Timeframe:	<input type="checkbox"/> Urgent	<input type="checkbox"/> 1 - 5 Years	<input type="checkbox"/> 6 - 10 Years
Comments:			

Element Photos



Comments:

Element Data

Element Group:	Barriers	Length:	0.19	(m)
Element Name:	Posts	Width:	0.19	(m)
Location:	East and West side	Height:	0.9	(m)
Material:	Wood	Count:	11	each side
Element Type:	Dimension Lumber	Total Quantity:	22	each
Environment:	Benign / Moderate / Severe	Limited Insp'n:	<input type="checkbox"/>	
Protection System:	Wood Preservative Treatment			Performance Deficiencies
Condition Data:	Units m ² / m each / % / all	Exc. 15	Good 7	
None				

Comments: One offset block twisted at the northwest side of structure. Light rotting on the top of all posts.

Performance Deficiencies:

Recommended Work:	<input type="checkbox"/> Minor Rehab	<input type="checkbox"/> Major Rehab	Maintenance Needs:
	<input type="checkbox"/> Replace	<input checked="" type="checkbox"/> None	
Timeframe:	<input type="checkbox"/> Urgent	<input type="checkbox"/> 1 - 5 Years	<input type="checkbox"/> 6 - 10 Years
Comments:	Straighten offset blocks		

Element Photos



Comments:

Municipal Structure Inspection Form
Wilson Lake Road Bridge 1

MTO Site Number:

Element Data

Element Group:	Barriers	Length:	3.81	(m)
Element Name:	Railing Systems	Width:	n/a	(m)
Location:	East and West sides of Deck	Height:	0.9	(m)
Material:	Steel	Count:	10	each side
Element Type:	Flex Beam	Total Quantity:	38.1	(m)
Environment:	Benign / Moderate / Severe	Limited Insp'n:	<input type="checkbox"/>	
Protection System:	Galvanized			Performance Deficiencies
Condition Data:	Units m ² m / each / % / all	Exc. 37.1	Good 1	
Poor				
None				
Comments:				
Performance Deficiencies:				
Recommended Work:	<input type="checkbox"/> Minor Rehab		<input type="checkbox"/> Major Rehab	
	<input type="checkbox"/> Replace		<input checked="" type="checkbox"/> None	
Timeframe:			Maintenance Needs:	
<input type="checkbox"/> Urgent <input type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years			<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Year	
Comments:				
Element Photos				
Comments:				

Municipal Structure Inspection Form
Wilson Lake Road Bridge 1

MTO Site Number:

Element Data

Element Group:	Approaches	Length:	6	(m)		
Element Name:	Wearing Surface	Width:	4.9	(m)		
Location:	East and West Approaches	Height:	n/a	(m)		
Material:	Gravel	Count:	2	each		
Element Type:	-	Total Quantity:	58.8	(m ²)		
Environment:	Benign / Moderate / Severe	Limited Insp'n:	<input type="checkbox"/>			
Protection System:	-			Performance Deficiencies		
Condition	Units	Exc.	Good	Fair	Poor	
Data:	m ² / m / each / % / all		58.8			None

Comments: Gravel approaching wearing surface. Light vegetation over sides of approaching entrances.

Performance Deficiencies:

Recommended Work:	<input type="checkbox"/> Minor Rehab	<input type="checkbox"/> Major Rehab	Maintenance Needs:
	<input type="checkbox"/> Replace	<input checked="" type="checkbox"/> None	
Timeframe:	<input type="checkbox"/> Urgent	<input type="checkbox"/> 1 - 5 Years	<input type="checkbox"/> 6 - 10 Years
Comments:	Trim back excess vegetation.		

Element Photos



Comments:

Municipal Structure Inspection Form
Wilson Lake Road Bridge 1

MTO Site Number:

Element Data

Element Group:	Approaches			Length:	n/a	(m)
Element Name:	Signage			Width:	n/a	(m)
Location:	North and South Approaches			Height:	n/a	(m)
Material:	-			Count:	2	each side
Element Type:	-			Total Quantity:	4	each
Environment:	Benign / Moderate / Severe			Limited Insp'n:	<input type="checkbox"/>	
Protection System:	-			Performance Deficiencies		
Condition Data:	Units m ² / m each / % / all	Exc. 4	Good			
Comments:						
Performance Deficiencies:						
Recommended Work:	<input type="checkbox"/> Minor Rehab		<input type="checkbox"/> Major Rehab		Maintenance Needs:	
	<input type="checkbox"/> Replace		<input checked="" type="checkbox"/> None			
Timeframe:	<input type="checkbox"/> Urgent		<input type="checkbox"/> 1 - 5 Years		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Year	
Comments:						
Element Photos						
Comments:						

Municipal Structure Inspection Form
Wilson Lake Road Bridge 1

MTO Site Number:

Element Data

Element Group:	Embankments and Streams	Length:	n/a	(m)		
Element Name:	Streams and Waterways	Width:	n/a	(m)		
Location:	-	Height:	n/a	(m)		
Material:	-	Count:	1	each		
Element Type:	-	Total Quantity:	1	all		
Environment:	Benign / Moderate / Severe	Limited Insp'n:	<input type="checkbox"/>			
Protection System:	-					
Condition	Units	Exc.	Good	Fair	Poor	Performance Deficiencies
Data:	m ² / m / each / % all		1			

Comments: Light beaver dam noted at the middle of structure.

Performance Deficiencies:

Recommended Work:	<input type="checkbox"/> Minor Rehab	<input type="checkbox"/> Major Rehab	Maintenance Needs:
	<input type="checkbox"/> Replace	<input checked="" type="checkbox"/> None	
Timeframe:	<input type="checkbox"/> Urgent	<input type="checkbox"/> 1 - 5 Years	<input type="checkbox"/> 6 - 10 Years
Comments:	Remove beaver dam.		

Element Photos



Comments:

Inventory Data:

Structure Name	<input type="text" value="Wilson Lake Road Bridge 2"/>		
Main Highway #	<input type="text"/>	On <input checked="" type="checkbox"/> or Under <input type="checkbox"/> Structure	Service on structure: <input type="checkbox"/> Navig. Water <input type="checkbox"/> Non-Navig. Water <input type="checkbox"/> Rail <input checked="" type="checkbox"/> Road <input type="checkbox"/> Ped. <input type="checkbox"/> Other
Location description	<input type="text" value="12.4 km Southwest of Hwy 11"/>	Service under	<input type="checkbox"/> Navig. Water <input checked="" type="checkbox"/> Non-Navig. Water <input type="checkbox"/> Rail <input type="checkbox"/> Road <input type="checkbox"/> Ped. <input type="checkbox"/> Other
Owner/Custodian	<input type="text" value="Municipality of Temagami"/>	LHRS:	<input type="text"/>
MTO Region	<input type="text" value="Northern"/>	LHRS offset:	<input type="text"/>
Regional Engineer	<input type="text"/>	Latitude:	<input n"="" type="text" value="46° 52' 38"/>
MTO Area	<input type="text" value="Sudbury"/>	Longitude:	<input type="text" value="79° 48' 36" w"=""/>
Old County	<input type="text"/>	Heritage Designation:	<input checked="" type="checkbox"/> Not Cons. <input type="checkbox"/> Cons./not App. <input type="checkbox"/> List/not Desig. <input type="checkbox"/> Desig./not List <input type="checkbox"/> Desig. & List
Township	<input type="text" value="Temagami"/>	Hwy Class:	Freeway <input type="checkbox"/> Arterial <input type="checkbox"/> Collector <input type="checkbox"/> Local <input checked="" type="checkbox"/>
Structure Type 1	<input type="text" value="Bailey Bridge (Triple-Single)"/>	Posted Speed	<input type="text"/>
Structure Material 1	<input type="text" value="Steel"/>	No. of Lanes	<input type="text" value="1"/>
Structure Type 2	<input type="text" value="Deck"/>	AADT	<input type="text"/>
Structure Material 2	<input type="text" value="Wood"/>	% Truck	<input type="text"/>
Total Deck Length	<input type="text" value="21.3"/> (m)	Travel Stream	<input type="text" value="W"/>
Overall Str. Width	<input type="text" value="5.49"/> (m)	Traffic Directional Bound	<input type="text" value="S-N"/>
Culvert length	<input type="text"/>	Inspection Route Sequence	<input type="text"/>
Total Deck Area	<input type="text" value="116.9"/> (sq.m)	Inspection Frequency	<input type="text" value="2"/> (years)
Roadway Width	<input type="text" value="3.3"/> (m)	Inspection Year	<input type="text" value="2023"/>
Skew Angle	<input type="text" value="0"/> (Degree)	Inspection Duration	<input type="text"/>
No. of Spans	<input type="text" value="1"/>	Interchange Number	<input type="text"/>
Span Lengths	<input type="text" value="21.3 (7 bays)"/>	Interchange Structure Number	<input type="text"/>
<u>For retaining wall:</u>		Min. Vertical Clearance	<input type="text"/> (m)
Total Wall Length	<input type="text"/> (m)	Detour Distance	<input type="text"/> (km)
Total Wall Area	<input type="text"/> (sq.m)	Fill on Structure	<input type="text"/> (m)
		Angle of Backfill	<input type="text"/> (Degree)

Rev 2018

Rev 2018

Rev 2018

Historical Data:			
Year Built	<input type="text"/>	Year of superstruct. constructed	<input type="text"/>
Last Reg OSIM Inspection	<input type="text" value="2021"/>	Year of Last Minor Rehab.	<input type="text"/>
Last Enh. OSIM Inspection	<input type="text"/>	Year of Last Major Rehab.	<input type="text" value="2011"/>
	<input type="text"/>	Current Load Limit	<input type="text" value="50/36/21"/> (tonnes)
Work History: (Date/description) 2011: Replaced all bearing timbers and approaching guide rail posts. Raised north end of bridge by installing additional bearing timbers to correct settlement.			
Investigation History: (Date/description)			

Scheduled Improvements:	
Regional Priority Number <input type="text"/>	Programmed Work Year <input type="text"/>
Nature of Program Work: None	

Appraisal Indices:		Comments
Fatigue	None	
Seismic	None	
Scour	None	
Flood	None	
Barrier	None	
Curb	None	
Load Capacity	None	

Rev2008
2018

Field Inspection Information:			
Date of Inspection:	June 20, 2023	Type of Inspection:	<input checked="" type="checkbox"/> Reg. OSIM <input type="checkbox"/> Enh. OSIM
Inspected By:	Kevin Louch, P.Eng.		
Others in Party:	Kaitlyn Hunt		
Enh. Access Equipment:	Measuring Tape, Camera, Hammer		
Special Access Equipment:			
Weather:	Sunny	Temperature:	28 °C

2008

Additional Investigations Required:	Priority		
	None	Normal	Urgent
Material Condition Survey	✓		
Detailed Deck Condition Survey:	✓		
Non-destructive Delamination Survey of Asphalt-Covered Deck:	✓		
Concrete Substructure Condition Survey:	✓		
Detailed Coating Condition Survey:	✓		
Detailed Timber Investigation	✓		
Post-Tensioned Strand Investigation	✓		
Underwater Investigation:	✓		
Fatigue Investigation:	✓		
Seismic Investigation:	✓		
Structure Evaluation:	✓		
Monitoring	✓		
Deformations, Settlements and Movements:		✓	
Crack Widths:	✓		
RSS Horizontal movements of face:	✓		
RSS Vertical movements of overall structure:	✓		
RSS Local movements or deterioration of facing elements:	✓		
RSS Horizontal movements within overall structure:	✓		
RSS Vertical movements within overall structure:	✓		
RSS Lateral earth pressure at the back of facing elements:	✓		
Investigation Notes: No further investigation required.			

2018

Rev

Overall Structure Notes:	Overall Bridge Condition: BCI 42
Recommended Work on Structure:	<input type="checkbox"/> None <input type="checkbox"/> Minor Rehab. <input type="checkbox"/> Major Rehab. <input checked="" type="checkbox"/> Replace
Timing of Recommended Work:	<input checked="" type="checkbox"/> 1 to 5 years <input type="checkbox"/> 6 to 10 years
Overall Comments:	Curbs are heavily deteriorated, deck wearing surface and barrier rails in poor condition, missing timber bearing section, and pitted cross bracing members.
Date of Next Inspection:	2025

Suspected Performance Deficiencies

- | | | |
|---|--|--|
| <p>01 Load carrying capacity</p> <p>02 Excessive deformations (deflections & rotations)</p> <p>03 Continuing settlement</p> <p>04 Continuing movements</p> <p>05 Seized bearings</p> | <p>06 Bearing not uniformly loaded/unstable</p> <p>07 Jammed expansion joint</p> <p>08 Pedestrian/vehicular hazard</p> <p>09 Rough riding surface</p> <p>10 Surface ponding</p> <p>11 Deck/Wall drainage</p> | <p>12 Slippery surfaces</p> <p>13 Flooding/channel blockage</p> <p>14 Undermining of foundation</p> <p>15 Unstable embankments</p> <p>16 Other performance deficiencies</p> |
|---|--|--|

Maintenance Needs

- | | | |
|--|---|---|
| <p>01 N/A</p> <p>02 Bridge Cleaning</p> <p>03 Railing System Repair</p> <p>04 N/A</p> <p>05 Bridge Deck Joint Repair</p> <p>06 N/A</p> | <p>07 Structural Steel Repair</p> <p>08 Concrete Repair</p> <p>09 Timber Repair</p> <p>10 Works for Modular bridges</p> <p>11 Animal/Pest Control</p> <p>12 Bridge Surface Repair</p> | <p>13 Erosion Control at Bridges</p> <p>14 Concrete Sealing</p> <p>15 N/A</p> <p>16 Works for Drainage System</p> <p>17 Sealing (Loose Concrete or ACR Steel)</p> <p>18 Other Maintenance</p> |
|--|---|---|

2018

Rev
2008

Municipal Structure Inspection Form
Wilson Lake Road Bridge 2

MTO Site Number:

Repair and Rehabilitation Required:		Priority			Estimated Construction Cost
Element	Repair and Rehabilitation Required	6 to 10 years	1 to 5 years	Urgent	
Bearing Cribs	Reset/reinstall missing timber		x		\$1,000
Deck WS	Replace		x		\$40,000
Floor Beams/Stringers	Sandblast and paint or replace		x		\$100,000
Barrier Rails	Replace damaged sections		x		\$40,000
Cross Bracing	Replace pitted braces		x		\$75,000
Total Cost					\$256,000

Associated Work:	Comments	Estimated Cost
Other:	Engineering (15%)	\$38,400
Contingencies:	Contingency (10%)	\$25,600
Total Cost		\$64,000

Total Repair and Rehabilitation Cost	\$320,000
---	------------------

Replacement Cost	\$700,000
-------------------------	------------------

Maintenance Required		Priority			Estimated Construction Cost
Element	Repair and Rehabilitation Required	2 year	Within 1 year	Urgent	
Abutments/Ramps	Monitor for movement	x			\$2,000
Bailey Panel/Bearings	Remove vegetation		x		\$1,000
Approaches	Regrade		x		\$2,000
Barrier Post	Rotate blocks back straight		x		\$1,000
Deck WS	Replace curbs		x		\$1,000
Total Maintenance Cost					\$7,000

Justification:

Section View: Facing North



Elevation View: Facing East



Comments:

Element Data

Element Group:	Abutments	Length:	n/a	(m)		
Element Name:	Bearing Cribs	Width:	2.0	(m)		
Location:	North and South	Height:	0.85	(m)		
Material:	Wood	Count:	4	each		
Element Type:	Bearing Timbers	Total Quantity:	6.8	(m ²)		
Environment:	<u>Benign</u> / Moderate / Severe	Limited Insp'n:	<input type="checkbox"/>			
Protection System:	Treated			Performance Deficiencies		
Condition Data:	Units: <u>m²</u> m / each / % / all	Exc.	Good		Fair	Poor
				6.8		None

Comments: Separate bearing crib constructed with 200x200 mm treated timber under each Bailey base plate. Northeast bearing crib is missing timber section. Minor rotation and settlement of northeast bearing crib.

Performance Deficiencies:

Recommended Work:	<input type="checkbox"/> Minor Rehab	<input type="checkbox"/> Major Rehab	Maintenance Needs:	
	<input checked="" type="checkbox"/> Replace	<input type="checkbox"/> None	<input type="checkbox"/> Urgent	<input type="checkbox"/> 1 Year <input checked="" type="checkbox"/> 2 Year
Timeframe:	<input type="checkbox"/> Urgent	<input checked="" type="checkbox"/> 1 - 5 Years	<input type="checkbox"/> 6 - 10 Years	Monitor for movement.
Comments: Reset bearing crib and reinstall missing timber section at northeast crib.				



Comments:

Element Data

Element Group:	Abutments	Length:	n/a	(m)		
Element Name:	Bearings	Width:	n/a	(m)		
Location:	North and South	Height:	n/a	(m)		
Material:	Steel	Count:	8	each		
Element Type:	Bailey Bearing	Total Quantity:	8	each		
Environment:	Benign / Moderate / Severe	Limited Insp'n:	<input checked="" type="checkbox"/>			
Protection System:	Galvanized			Performance Deficiencies		
Condition	Units	Exc.	Good		Fair	Poor
Data:	m ² / m each / % / all			8		None

Comments: Bearing covered with vegetation and debris. Moderate corrosion noted on exposed steel.

Performance Deficiencies:

Recommended Work:	<input type="checkbox"/> Minor Rehab	<input type="checkbox"/> Major Rehab	Maintenance Needs:
	<input type="checkbox"/> Replace	<input checked="" type="checkbox"/> None	
Timeframe:	<input type="checkbox"/> Urgent	<input type="checkbox"/> 1 - 5 Years	<input type="checkbox"/> 6 - 10 Years
Comments:	Clear vegetation from bearing.		



Comments:

Element Data

Element Group:	Abutments	Length:	n/a	(m)		
Element Name:	Base Plate	Width:	n/a	(m)		
Location:	North and South	Height:	n/a	(m)		
Material:	Steel	Count:	4	each		
Element Type:	Bailey Base Plate	Total Quantity:	4	each		
Environment:	Benign / Moderate / Severe	Limited Insp'n:	<input checked="" type="checkbox"/>			
Protection System:	Galvanized			Performance Deficiencies		
Condition	Units	Exc.	Good		Fair	Poor
Data:	m ² / m each / % / all			4		None

Comments: Bearing covered with vegetation and debris. Moderate corrosion noted on exposed steel.

Performance Deficiencies:

Recommended Work:	<input type="checkbox"/> Minor Rehab	<input type="checkbox"/> Major Rehab	Maintenance Needs:
	<input type="checkbox"/> Replace	<input checked="" type="checkbox"/> None	
Timeframe:	<input type="checkbox"/> Urgent	<input type="checkbox"/> 1 - 5 Years	<input type="checkbox"/> 6 - 10 Years
Comments:	Clear vegetation from bearing.		



Comments:

Municipal Structure Inspection Form
Wilson Lake Road Bridge 2

MTO Site Number:

Element Data

Element Group:	Main Longitudinal Elements	Length:	n/a	(m)		
Element Name:	Floor Beams	Width:	n/a	(m)		
Location:	-	Height:	n/a	(m)		
Material:	Steel	Count:	14	each		
Element Type:	Bailey Transom	Total Quantity:	14	each		
Environment:	Benign / Moderate / Severe	Limited Insp'n:	<input checked="" type="checkbox"/>			
Protection System:	Galvanized					
Condition	Units	Exc.	Good	Fair	Poor	Performance Deficiencies
Data:	m ² / m each / % / all			14		

Comments: Load carry capacity deficiencies (2 transoms per bay). Medium corrosion noted.

Performance Deficiencies:

Recommended Work:	<input checked="" type="checkbox"/> Minor Rehab	<input type="checkbox"/> Major Rehab	Maintenance Needs:		
	<input type="checkbox"/> Replace	<input type="checkbox"/> None	<input type="checkbox"/> Urgent	<input type="checkbox"/> 1 Year	<input type="checkbox"/> 2 Year
Timeframe:	<input type="checkbox"/> Urgent	<input checked="" type="checkbox"/> 1 - 5 Years	<input type="checkbox"/> 6 - 10 Years		
Comments: Sandblast structural steel and repaint, or replace bridge.					



Comments:

Municipal Structure Inspection Form
Wilson Lake Road Bridge 2

MTO Site Number:

Element Data

Element Group:	Main Longitudinal Elements	Length:	n/a	(m)	
Element Name:	Stringers	Width:	n/a	(m)	
Location:	-	Height:	n/a	(m)	
Material:	Steel	Count:	45	each	
Element Type:	Bailey Stringer	Total Quantity:	45	each	
Environment:	<u>Benign</u> / Moderate / Severe	Limited Insp'n:	<input checked="" type="checkbox"/>		
Protection System:	Galvanized			Performance Deficiencies	
Condition Data:	Units m ² / m <u>each</u> / % / all	Exc.	Good		Fair
				Poor	None
Comments: Visual deflection noted when vehicle crosses the bridge. Medium corrosion noted.					
Performance Deficiencies:					
Recommended Work:	<input checked="" type="checkbox"/> Minor Rehab	<input type="checkbox"/> Major Rehab		Maintenance Needs:	
	<input type="checkbox"/> Replace	<input type="checkbox"/> None			<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Year
Timeframe:	<input type="checkbox"/> Urgent	<input checked="" type="checkbox"/> 1 - 5 Years	<input type="checkbox"/> 6 - 10 Years		
Comments: Sandblast structural steel and repaint, or replace bridge.					
Comments:					

Element Data

Element Group:	Approaches	Length:	3.3	(m)
Element Name:	Approach Ramps	Width:	3.6	(m)
Location:	North and South	Height:	0.13	(m)
Material:	Steel	Count:	2	each
Element Type:	Bailey Ramp	Total Quantity:	23.8	(m ²)
Environment:	Benign Moderate Severe	Limited Insp'n:	<input checked="" type="checkbox"/>	
Protection System:	Galvanized			Performance Deficiencies
Condition Data:	Units: m² m / each / % / all	Exc.	Good: 10	
			Poor: 5	None

Comments: Permanant deformation at ramps where vehicles enter onto bridge.

Performance Deficiencies:

Recommended Work:	<input type="checkbox"/> Minor Rehab	<input type="checkbox"/> Major Rehab	Maintenance Needs:
	<input type="checkbox"/> Replace	<input checked="" type="checkbox"/> None	
Timeframe:	<input type="checkbox"/> Urgent	<input type="checkbox"/> 1 - 5 Years	<input type="checkbox"/> 6 - 10 Years
Comments:	Monitor for further deflection.		



Comments:

Municipal Structure Inspection Form
Wilson Lake Road Bridge 2

MTO Site Number:

Element Data

Element Group:	Barrier	Length:	0.2	(m)		
Element Name:	Posts	Width:	0.2	(m)		
Location:	West and East sides	Height:	1.0	(m)		
Material:	Wood	Count:	9	each		
Element Type:	Post	Total Quantity:	9	each		
Environment:	Benign Moderate Severe	Limited Insp'n:	<input type="checkbox"/>			
Protection System:	-					
Condition	Units	Exc.	Good	Fair	Poor	Performance Deficiencies
Data:	m ² / m each / % / all			6	3	

Comments: Wood offset blocks twisted at northeast and southeast corner.

Performance Deficiencies:

Recommended Work:	<input type="checkbox"/> Minor Rehab	<input type="checkbox"/> Major Rehab	Maintenance Needs:
	<input type="checkbox"/> Replace	<input checked="" type="checkbox"/> None	
Timeframe:	<input type="checkbox"/> Urgent	<input type="checkbox"/> 1 - 5 Years	<input type="checkbox"/> 6 - 10 Years
Comments:	Reset rotated offset blocks.		



Comments:

Element Data

Element Group:	Barrier	Length:	3.81	(m)	
Element Name:	Railing System	Width:	n/a	(m)	
Location:	West and East sides	Height:	0.7	(m)	
Material:	Steel	Count:	22	each	
Element Type:	Flex Beam	Total Quantity:	83.8	(m)	
Environment:	Benign / Moderate / Severe	Limited Insp'n:	<input type="checkbox"/>		
Protection System:	Galvanized			Performance Deficiencies	
Condition Data:	Units m ² m each / % / all	Exc.	Good		Fair
			30	40	Poor 13.8

Comments: SBGR end treatments are not as per OPSD Standards for approach terminal end treatments. Minor impact damage throughout. Severe damage to section on northeast end. Snowplow damage throughout.

Performance Deficiencies:

Recommended Work:	<input type="checkbox"/> Minor Rehab	<input type="checkbox"/> Major Rehab	Maintenance Needs:	
	<input checked="" type="checkbox"/> Replace	<input type="checkbox"/> None	<input type="checkbox"/> Urgent	<input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Year
Timeframe:	<input type="checkbox"/> Urgent	<input checked="" type="checkbox"/> 1 - 5 Years	<input type="checkbox"/> 6 - 10 Years	
Comments: Replace damaged SBGR.				



Comments:

Municipal Structure Inspection Form
Wilson Lake Road Bridge 2

MTO Site Number:

Element Data

Element Group:	Deck	Length:	27.4	(m) including ramps		
Element Name:	Deck Top	Width:	3.6	(m)		
Location:	-	Height:	0.038	(m)		
Material:	Wood	Count:	n/a	each		
Element Type:	Dimension Lumber	Total Quantity:	98.6	(m ²)		
Environment:	Benign Moderate Severe	Limited Insp'n:	<input checked="" type="checkbox"/>			
Protection System:	Treated			Performance Deficiencies		
Condition	Units	Exc.	Good		Fair	Poor
Data:	m ² m / each / % / all		49.3	49.3		None
Comments: Dimensional 38x140 mm timber boards under wearing surface. Minor splits and deterioration noted throughout. Top inspection obscured by timber deck wearing surface.						
Performance Deficiencies:						
Recommended Work:	<input type="checkbox"/> Minor Rehab		<input type="checkbox"/> Major Rehab		Maintenance Needs:	
	<input type="checkbox"/> Replace		<input checked="" type="checkbox"/> None			<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Year
Timeframe:	<input type="checkbox"/> Urgent		<input type="checkbox"/> 1 - 5 Years		<input type="checkbox"/> 6 - 10 Years	
Comments:						
Comments:						


Element Data

Element Group:	Deck	Length:	27.4	(m) including ramps		
Element Name:	Wearing Surface	Width:	3.3	(m)		
Location:	-	Height:	0.038	(m)		
Material:	Wood	Count:	n/a	each		
Element Type:	Dimension Lumber	Total Quantity:	90.4	(m ²)		
Environment:	Benign / Moderate / Severe	Limited Insp'n:	<input type="checkbox"/>			
Protection System:	-					
Condition	Units	Exc.	Good	Fair	Poor	Performance Deficiencies
Data:	m² m / each / % / all			30	60.4	

Comments: Timber curbs are in poor condition. Bolts are bent and wood is split with checking throughout. Curb is broken throughout sections. Cracking throughout with moderate wearing in wheel path. Visual settlement at north bearing.

Performance Deficiencies:

Recommended Work:	<input type="checkbox"/> Minor Rehab	<input type="checkbox"/> Major Rehab	Maintenance Needs:
	<input checked="" type="checkbox"/> Replace	<input type="checkbox"/> None	
Timeframe:	<input type="checkbox"/> Urgent	<input type="checkbox"/> 1 - 5 Years	<input checked="" type="checkbox"/> 6 - 10 Years
Comments: Replace timber wearing surface.			Replace timber Curbs.



Comments:

Element Data

Element Group:	Truss	Length:	n/a	(m)		
Element Name:	Bailey Panel	Width:	n/a	(m)		
Location:	East and West	Height:	n/a	(m)		
Material:	Steel	Count:	42	each		
Element Type:	Bailey Panels	Total Quantity:	42	each		
Environment:	Benign Moderate Severe	Limited Insp'n:	<input type="checkbox"/>			
Protection System:	Galvanized			Performance Deficiencies		
Condition Data:	Units	Exc.	Good		Fair	Poor
	m ² / m each % / all			42		None

Comments: Load carry capacity deficiency, one raker at southeast corner deformed. Severe corrosion and flaking of paint noted throughout. Exterior panels appear to be older than the interior two runs with severe galvanize flaking. Tree protruding up at west side.

Performance Deficiencies:

Recommended Work:	<input type="checkbox"/> Minor Rehab	<input type="checkbox"/> Major Rehab	Maintenance Needs:
	<input type="checkbox"/> Replace	<input checked="" type="checkbox"/> None	
Timeframe:	<input type="checkbox"/> Urgent	<input type="checkbox"/> 1 - 5 Years	<input type="checkbox"/> 6 - 10 Years
Comments:	Remove all vegetation in paneling.		



Comments:

Element Data

Element Group:	Truss	Length:	n/a	(m)		
Element Name:	Cross Braces	Width:	n/a	(m)		
Location:	Under	Height:	n/a	(m)		
Material:	Steel	Count:	14	each		
Element Type:	Cross Bracing	Total Quantity:	14.0	each		
Environment:	Benign Moderate Severe	Limited Insp'n:	<input type="checkbox"/>			
Protection System:	-					
Condition	Units	Exc.	Good	Fair	Poor	Performance Deficiencies
Data:	m ² / m each / % / all			13	1	

Comments: Moderate corrosion throughout. One cross bracing at south side has severe pitting.

Performance Deficiencies:

Recommended Work:	<input type="checkbox"/> Minor Rehab	<input type="checkbox"/> Major Rehab	Maintenance Needs:		
	<input checked="" type="checkbox"/> Replace	<input type="checkbox"/> None	<input type="checkbox"/> Urgent	<input type="checkbox"/> 1 Year	<input type="checkbox"/> 2 Year
Timeframe:	<input type="checkbox"/> Urgent	<input checked="" type="checkbox"/> 1 - 5 Years	<input type="checkbox"/> 6 - 10 Years		
Comments: Replace severely pitted cross bracing members.					



Comments:

Municipal Structure Inspection Form
Wilson Lake Road Bridge 2

MTO Site Number:

Element Data

Element Group:	Approaches	Length:	6	(m)		
Element Name:	Wearing Surface	Width:	4	(m)		
Location:	North and South	Height:	n/a	(m)		
Material:	Granular	Count:	2	each		
Element Type:	-	Total Quantity:	48.0	(m ²)		
Environment:	Benign / Moderate / Severe	Limited Insp'n:	<input type="checkbox"/>			
Protection System:	-					
Condition	Units	Exc.	Good	Fair	Poor	Performance Deficiencies
Data:	m² m / each / % / all		40	4	4	

Comments: Potholes at north approach and south ramping.

Performance Deficiencies:

Recommended Work:	<input type="checkbox"/> Minor Rehab	<input type="checkbox"/> Major Rehab	Maintenance Needs:
	<input type="checkbox"/> Replace	<input checked="" type="checkbox"/> None	
Timeframe:	<input type="checkbox"/> Urgent	<input type="checkbox"/> 1 - 5 Years	<input type="checkbox"/> 6 - 10 Years
Comments:	Regrade potholes and ramping.		

Comments:

Municipal Structure Inspection Form
Wilson Lake Road Bridge 2

MTO Site Number:

Element Data

Element Group:	Embankments and Streams	Length:	n/a	(m)		
Element Name:	Streams and Waterways	Width:	n/a	(m)		
Location:	-	Height:	n/a	(m)		
Material:	-	Count:	1	each		
Element Type:	-	Total Quantity:	1	all		
Environment:	Benign / Moderate / Severe	Limited Insp'n:	<input type="checkbox"/>			
Protection System:	-					
Condition	Units	Exc.	Good	Fair	Poor	Performance Deficiencies
Data:	m ² / m / each / % all		1			

Comments: Streams and embankments are in good condition.

Performance Deficiencies:

Recommended Work:	<input type="checkbox"/> Minor Rehab	<input type="checkbox"/> Major Rehab	Maintenance Needs:		
	<input type="checkbox"/> Replace	<input checked="" type="checkbox"/> None	<input type="checkbox"/> Urgent	<input type="checkbox"/> 1 Year	<input type="checkbox"/> 2 Year
Timeframe:	<input type="checkbox"/> Urgent	<input type="checkbox"/> 1 - 5 Years	<input type="checkbox"/> 6 - 10 Years		
Comments:					

Comments:

Municipal Structure Inspection Form
Wilson Lake Road Bridge 2

MTO Site Number:

Element Data

Element Group:	Approaches	Length:	n/a	(m)		
Element Name:	Signage	Width:	n/a	(m)		
Location:	North and South	Height:	n/a	(m)		
Material:	-	Count:	6	each		
Element Type:	-	Total Quantity:	6.0	each		
Environment:	Benign / Moderate / Severe	Limited Insp'n:	<input type="checkbox"/>			
Protection System:	-					
Condition	Units	Exc.	Good	Fair	Poor	Performance Deficiencies
Data:	m ² / m / each / % / all		5	1		

Comments: Vegetation has encroached on roadway, partially obscuring signage.

Performance Deficiencies:

Recommended Work:	<input type="checkbox"/> Minor Rehab	<input type="checkbox"/> Major Rehab	Maintenance Needs:
	<input type="checkbox"/> Replace	<input checked="" type="checkbox"/> None	
Timeframe:	<input type="checkbox"/> Urgent	<input type="checkbox"/> 1 - 5 Years	<input type="checkbox"/> 6 - 10 Years
Comments:	Clear vegetation		

Comments:

Inventory Data:

Structure Name	<input type="text" value="Temagami Lake Access Road Bridge"/>		
Main Highway #	<input type="text"/>	On <input checked="" type="checkbox"/> or Under <input type="checkbox"/> Structure	Service on structure: <input type="checkbox"/> Navig. Water <input type="checkbox"/> Non-Navig. Water <input type="checkbox"/> Rail <input checked="" type="checkbox"/> Road <input type="checkbox"/> Ped. <input type="checkbox"/> Other
Location description	<input type="text" value="5.0 km West of Hwy 11"/>	Service under	<input type="checkbox"/> Navig. Water <input checked="" type="checkbox"/> Non-Navig. Water <input type="checkbox"/> Rail <input type="checkbox"/> Road <input type="checkbox"/> Ped. <input type="checkbox"/> Other
Owner/Custodian	<input type="text" value="Municipality of Temagami"/>	LHRS:	<input type="text"/>
MTO Region	<input type="text" value="Northern"/>	LHRS offset:	<input type="text"/>
Regional Engineer	<input type="text"/>	Latitude:	<input n"="" type="text" value="47° 00' 21"/>
MTO Area	<input type="text" value="Sudbury"/>	Longitude:	<input type="text" value="79° 52' 47" w"=""/>
Old County	<input type="text"/>	Heritage Designation:	<input checked="" type="checkbox"/> Not Cons. <input type="checkbox"/> Cons./not App. <input type="checkbox"/> List/not Desig. <input type="checkbox"/> Desig./not List <input type="checkbox"/> Desig. & List
Township	<input type="text" value="Temagami"/>	Hwy Class:	Freeway <input type="checkbox"/> Arterial <input type="checkbox"/> Collector <input type="checkbox"/> Local <input checked="" type="checkbox"/>
Structure Type 1	<input type="text" value="Girder"/>	Posted Speed	<input type="text" value="50 km/h"/>
Structure Material 1	<input type="text" value="Steel"/>	No. of Lanes	<input type="text" value="2"/>
Structure Type 2	<input type="text" value="Deck"/>	AADT	<input type="text"/>
Structure Material 2	<input type="text" value="Wood/Fiber Glass"/>	% Truck	<input type="text"/>
Total Deck Length	<input type="text" value="7.3"/> (m)	Travel Stream	<input type="text" value="N"/>
Overall Str. Width	<input type="text" value="8.1"/> (m)	Traffic Directional Bound	<input type="text" value="W-E"/>
Culvert length	<input type="text"/>	Inspection Route Sequence	<input type="text"/>
Total Deck Area	<input type="text" value="59.1"/> (sq.m)	Inspection Frequency	<input type="text" value="2"/> (years)
Roadway Width	<input type="text" value="7.9"/> (m)	Inspection Year	<input type="text" value="2023"/>
Skew Angle	<input type="text" value="30"/> (Degree)	Inspection Duration	<input type="text"/>
No. of Spans	<input type="text" value="1"/>	Interchange Number	<input type="text"/>
Span Lengths	<input type="text" value="6.15"/> (m)	Interchange Structure Number	<input type="text"/>
<u>For retaining wall:</u>			
Total Wall Length	<input type="text"/> (m)	Min. Vertical Clearance	<input type="text"/> (m)
Total Wall Area	<input type="text"/> (sq.m)	Detour Distance	<input type="text"/> (km)
		Fill on Structure	<input type="text"/> (m)
		Angle of Backfill	<input type="text"/> (Degree)

Rev 2018

Rev 2018

Rev 2018

Historical Data:			
Year Built	<input type="text" value="2010"/>	Year of superstruct. constructed	<input type="text"/>
Last Reg OSIM Inspection	<input type="text" value="2021"/>	Year of Last Minor Rehab.	<input type="text"/>
Last Enh. OSIM Inspection	<input type="text"/>	Year of Last Major Rehab.	<input type="text" value="2022"/>
	<input type="text"/>	Current Load Limit	<input type="text"/> (tonnes)
Work History: (Date/description) 2022: West abutment undermining grouted solid, signs and guide rails replaced.			
Investigation History: (Date/description)			

Scheduled Improvements:	
Regional Priority Number <input type="text"/>	Programmed Work Year <input type="text"/>
Nature of Program Work: None	

Appraisal Indices:		Comments
Fatigue	None	
Seismic	None	
Scour	None	
Flood	None	
Barrier	None	
Curb	None	
Load Capacity	None	

Rev2008
2018

Field Inspection Information:			
Date of Inspection:	June 20, 2023	Type of Inspection:	<input checked="" type="checkbox"/> Reg. OSIM <input type="checkbox"/> Enh. OSIM
Inspected By:	Kevin Louch, P.Eng.		
Others in Party:	Kaitlyn Hunt		
Enh. Access Equipment:	Measuring Tape, Camera, Hammer		
Special Access Equipment:			
Weather:	Sunny	Temperature:	27 °C

2008

Additional Investigations Required:	Priority		
	None	Normal	Urgent
Material Condition Survey	✓		
Detailed Deck Condition Survey:	✓		
Non-destructive Delamination Survey of Asphalt-Covered Deck:	✓		
Concrete Substructure Condition Survey:	✓		
Detailed Coating Condition Survey:	✓		
Detailed Timber Investigation	✓		
Post-Tensioned Strand Investigation	✓		
Underwater Investigation:	✓		
Fatigue Investigation:	✓		
Seismic Investigation:	✓		
Structure Evaluation:	✓		
Monitoring	✓		
Deformations, Settlements and Movements:	✓		
Crack Widths:	✓		
RSS Horizontal movements of face:	✓		
RSS Vertical movements of overall structure:	✓		
RSS Local movements or deterioration of facing elements:	✓		
RSS Horizontal movements within overall structure:	✓		
RSS Vertical movements within overall structure:	✓		
RSS Lateral earth pressure at the back of facing elements:	✓		
Investigation Notes: No further investigation required.			

2018

Overall Structure Notes:	Overall Bridge Condition:
	BCI 73
Recommended Work on Structure:	<input type="checkbox"/> None <input type="checkbox"/> Minor Rehab. <input checked="" type="checkbox"/> Major Rehab. <input type="checkbox"/> Replace
Timing of Recommended Work:	<input checked="" type="checkbox"/> 1 to 5 years <input type="checkbox"/> 6 to 10 years
Overall Comments:	East bin wall now undermined similar to west wall - to be repaired.
Date of Next Inspection:	2025

Rev

Suspected Performance Deficiencies

- | | | |
|--|---|--|
| 01 Load carrying capacity | 06 Bearing not uniformly loaded/unstable | 12 Slippery surfaces |
| 02 Excessive deformations (deflections & rotations) | 07 Jammed expansion joint | 13 Flooding/channel blockage |
| 03 Continuing settlement | 08 Pedestrian/vehicular hazard | 14 Undermining of foundation |
| 04 Continuing movements | 09 Rough riding surface | 15 Unstable embankments |
| 05 Seized bearings | 10 Surface ponding | 16 Other performance deficiencies |
| | 11 Deck/Wall drainage | |

Maintenance Needs

- | | | |
|------------------------------------|-------------------------------------|---|
| 01 N/A | 07 Structural Steel Repair | 13 Erosion Control at Bridges |
| 02 Bridge Cleaning | 08 Concrete Repair | 14 Concrete Sealing |
| 03 Railing System Repair | 09 Timber Repair | 15 N/A |
| 04 N/A | 10 Works for Modular bridges | 16 Works for Drainage System |
| 05 Bridge Deck Joint Repair | 11 Animal/Pest Control | 17 Sealing (Loose Concrete or ACR Steel) |
| 06 N/A | 12 Bridge Surface Repair | 18 Other Maintenance |

2018

Rev
2008

Municipal Structure Inspection Form
Temagami Lake Access Road Bridge

MTO Site Number:

Repair and Rehabilitation Required:		Priority			Estimated Construction Cost
Element	Repair and Rehabilitation Required	6 to 10 years	1 to 5 years	Urgent	
Abutment Wall	Rehabilitation of East Undermining		x		\$60,000
Slope protection	Rehabilitation of East Gabions		x		\$30,000
Total Cost					\$90,000

Associated Work:	Comments	Estimated Cost
Other:	Engineering (15%)	\$13,500
Contingencies:	Contingency (10%)	\$9,000
Total Cost		\$22,500

Total Repair and Rehabilitation Cost	\$112,500
---	------------------

Replacement Cost	\$600,000
-------------------------	------------------

Maintenance Required		Priority			Estimated Construction Cost
Element	Repair and Rehabilitation Required	2 year	Within 1 year	Urgent	
Streams	Remove daming		x		\$1,000
Approach WS	Remove gravel on top		x		\$1,000
Deck WS	Removal gravel on top		x		\$1,000
Total Maintenance Cost					\$3,000

Justification:

Section View: West



Elevation View: North



Comments:

Municipal Structure Inspection Form
Temagami Lake Access Road Bridge

MTO Site Number:

Element Data

Element Group:	Abutments	Length:	n/a	(m)		
Element Name:	Abutment Wall	Width:	11.36	(m)		
Location:	West and East	Height:	1.22	(m)		
Material:	Steel	Count:	2	each		
Element Type:	Steel Panels	Total Quantity:	27.7	(m ²)		
Environment:	<u>Benign</u> / Moderate / Severe	Limited Insp'n:	<input type="checkbox"/>			
Protection System:	Steel Coating					
Condition	Units	Exc.	Good	Fair	Poor	Performance Deficiencies
Data:	m ² m / each / % / all		22.2		5.5	

Comments: Moderate undermining of the abutment wall in the northeast quadrant. Large crack noted in southeast corner of bridge's concrete ballast wall. Steel coating flaking and light corrosion at the base of abutment wall.

Performance Deficiencies:

Recommended Work:	<input type="checkbox"/> Minor Rehab	<input checked="" type="checkbox"/> Major Rehab	Maintenance Needs:		
	<input type="checkbox"/> Replace	<input type="checkbox"/> None	<input type="checkbox"/> Urgent	<input type="checkbox"/> 1 Year	<input type="checkbox"/> 2 Year
Timeframe:	<input type="checkbox"/> Urgent	<input checked="" type="checkbox"/> 1 - 5 Years	<input type="checkbox"/> 6 - 10 Years		
Comments: Repair the undermining of the east abutment wall.					

Element Photos



Comments:

Element Data

Element Group:	Abutments	Length:	2.15	(m)		
Element Name:	Wingwall	Width:	n/a	(m)		
Location:	NE, NW, SE, SW	Height:	0.9	(m) avg		
Material:	Steel	Count:	4	each		
Element Type:	Steel Panel	Total Quantity:	7.8	(m ²)		
Environment:	Benign / Moderate / Severe	Limited Insp'n:	<input type="checkbox"/>			
Protection System:	Steel Coating					
Condition	Units	Exc.	Good	Fair	Poor	Performance Deficiencies
Data:	m ² m / each / % / all		7	0.8		

Comments: Steel coating flaking and light corrosion at wingwall bases.

Performance Deficiencies:

Recommended Work:	<input type="checkbox"/> Minor Rehab	<input type="checkbox"/> Major Rehab	Maintenance Needs:		
	<input type="checkbox"/> Replace	<input checked="" type="checkbox"/> None	<input type="checkbox"/> Urgent	<input type="checkbox"/> 1 Year	<input type="checkbox"/> 2 Year
Timeframe:	<input type="checkbox"/> Urgent	<input type="checkbox"/> 1 - 5 Years	<input type="checkbox"/> 6 - 10 Years		
Comments:					

Element Photos



Comments:

Municipal Structure Inspection Form
 Temagami Lake Access Road Bridge

MTO Site Number:

Element Data

Element Group:	Main Longitudinal Elements	Length:	2	(m) both ends total
Element Name:	Girders	Width:	0.31	(m)
Location:	Ends	Height:	0.3	(m)
Material:	Steel	Count:	5	each
Element Type:	W Section	Total Quantity:	15.3	(m ²)
Environment:	Benign Moderate Severe	Limited Insp'n:	<input type="checkbox"/>	
Protection System:	Steel Coating			Performance Deficiencies
Condition Data:	Units m ² / m / each / % / all	Exc.	Good 15	
Poor				
None				

Comments: Moderate corrosion showing through steel coating on central beam at west abutment wall.

Performance Deficiencies:

Recommended Work:	<input type="checkbox"/> Minor Rehab	<input type="checkbox"/> Major Rehab	Maintenance Needs:
	<input type="checkbox"/> Replace	<input checked="" type="checkbox"/> None	
Timeframe:	<input type="checkbox"/> Urgent	<input type="checkbox"/> 1 - 5 Years	<input type="checkbox"/> 6 - 10 Years
Comments:			

Element Photos



Comments:

Element Data

Element Group:	Main Longitudinal Elements	Length:	5.3	(m)	
Element Name:	Girders	Width:	0.31	(m)	
Location:	Middle	Height:	0.3	(m)	
Material:	Steel	Count:	5	each	
Element Type:	W Section	Total Quantity:	40.5	(m ²)	
Environment:	Benign / Moderate / Severe	Limited Insp'n:	<input type="checkbox"/>		
Protection System:	Steel Coating			Performance Deficiencies	
Condition Data:	Units	Exc.	Good		Fair
	m ² / m / each / % / all		39	1.5	

Comments: Numerous redundant bolt holes were observed in the girders bottom flange. Girders were pre-assembled into groups with 3 and 2 girders respectively and jointed together in the field with one single transverse link member at the mid-span.

Performance Deficiencies:

Recommended Work:	<input type="checkbox"/> Minor Rehab	<input type="checkbox"/> Major Rehab	Maintenance Needs:
	<input type="checkbox"/> Replace	<input checked="" type="checkbox"/> None	
Timeframe:	<input type="checkbox"/> Urgent	<input type="checkbox"/> 1 - 5 Years	<input type="checkbox"/> 6 - 10 Years
Comments:			

Element Photos



Comments:

Municipal Structure Inspection Form
Temagami Lake Access Road Bridge

MTO Site Number:

Element Data

Element Group:	Main Longitudinal Elements	Length:	2.06	(m)		
Element Name:	Diaphragms	Width:	0.1	(m)		
Location:	End	Height:	0.15	(m)		
Material:	Steel	Count:	6	each		
Element Type:	L-section	Total Quantity:	6	each		
Environment:	Benign Moderate Severe	Limited Insp'n:	<input checked="" type="checkbox"/>			
Protection System:	Steel Coating			Performance Deficiencies		
Condition	Units	Exc.	Good		Fair	Poor
Data:	m ² / m each / % / all		6			None
Comments: No end diaphragm between two pre-assembled girder sections.						
Performance Deficiencies:						
Recommended Work:	<input type="checkbox"/> Minor Rehab		<input type="checkbox"/> Major Rehab		Maintenance Needs:	
	<input type="checkbox"/> Replace		<input checked="" type="checkbox"/> None			<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Year
Timeframe:	<input type="checkbox"/> Urgent <input type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years					
Comments:						
Element Photos						
Comments:						

Element Data

Element Group:	Main Longitudinal Elements	Length:	2.06, 1	(m)		
Element Name:	Diaphragms	Width:	0.31	(m)		
Location:	Intermediate	Height:	0.3	(m)		
Material:	Steel	Count:	6-2.06, 3-1	(m) each		
Element Type:	W Section	Total Quantity:	9	each		
Environment:	Benign / Moderate / Severe	Limited Insp'n:	<input checked="" type="checkbox"/>			
Protection System:	Steel Coating					
Condition	Units	Exc.	Good	Fair	Poor	Performance Deficiencies
Data:	m ² / m / each / % / all		7	2		

Comments: No intermediate diaphragms between two pre-assembled sections, only one link member.

Performance Deficiencies:

Recommended Work:	<input type="checkbox"/> Minor Rehab	<input type="checkbox"/> Major Rehab	Maintenance Needs:
	<input type="checkbox"/> Replace	<input checked="" type="checkbox"/> None	
Timeframe:	<input type="checkbox"/> Urgent	<input type="checkbox"/> 1 - 5 Years	<input type="checkbox"/> 6 - 10 Years
Comments:			

Element Photos



Comments:

Element Data

Element Group:	Coating	Length:	n/a	(m)		
Element Name:	Structural Steel	Width:	n/a	(m)		
Location:	Ends	Height:	n/a	(m)		
Material:	-	Count:	n/a	each		
Element Type:	-	Total Quantity:	17.4	(m ²)		
Environment:	Benign Moderate Severe	Limited Insp'n:	<input type="checkbox"/>			
Protection System:	-					
Condition	Units	Exc.	Good	Fair	Poor	Performance Deficiencies
Data:	m ² / m / each / % / all		15.4	2		None

Comments: Steel structure has been repainted. Light corrosion and efflorescence at bottom middle of west abutment wall. Moderate corrosion at the bottom of central girder at west abutment wall.

Performance Deficiencies:

Recommended Work:	<input type="checkbox"/> Minor Rehab	<input type="checkbox"/> Major Rehab	Maintenance Needs:
	<input type="checkbox"/> Replace	<input checked="" type="checkbox"/> None	
Timeframe:	<input type="checkbox"/> Urgent	<input type="checkbox"/> 1 - 5 Years	<input type="checkbox"/> 6 - 10 Years
Comments:			

Element Photos



Comments:

Municipal Structure Inspection Form
Temagami Lake Access Road Bridge

MTO Site Number:

Element Data

Element Group:	Coating	Length:	n/a	(m)		
Element Name:	Structural Steel	Width:	n/a	(m)		
Location:	Middle	Height:	n/a	(m)		
Material:	-	Count:	n/a	each		
Element Type:	-	Total Quantity:	62.5	(m ²)		
Environment:	<u>Benign</u> / Moderate / Severe	Limited Insp'n:	<input type="checkbox"/>			
Protection System:	-					
Condition	Units	Exc.	Good	Fair	Poor	Performance Deficiencies
Data:	m ² / m / each / % / all		60	2.5		
Comments: Steel structure repainted. Light corrosion on middle girder						
Performance Deficiencies:						
Recommended Work:	<input type="checkbox"/> Minor Rehab		<input type="checkbox"/> Major Rehab		Maintenance Needs:	
	<input type="checkbox"/> Replace		<input checked="" type="checkbox"/> None		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Year	
Timeframe:	<input type="checkbox"/> Urgent		<input type="checkbox"/> 1 - 5 Years		<input type="checkbox"/> 6 - 10 Years	
Comments:						
Element Photos						
Comments:						

Municipal Structure Inspection Form
Temagami Lake Access Road Bridge

MTO Site Number:

Element Data

Element Group:	Decks	Length:	7.3	(m)		
Element Name:	Deck Top	Width:	8.1	(m)		
Location:	-	Height:	0.2	(m)		
Material:	Wood-Fibre Glass	Count:	n/a	each		
Element Type:	Transverse Laminate Deck	Total Quantity:	59.1	(m ²)		
Environment:	Benign Moderate Severe	Limited Insp'n:	<input checked="" type="checkbox"/>			
Protection System:	Treated					
Condition	Units	Exc.	Good	Fair	Poor	Performance Deficiencies
Data:	m ² / m / each / % / all		59.1			None

Comments: Deck top covered by 125 mm of gravel and surface treatment, condition unknown. Based on wearing surface and soffit.

Performance Deficiencies:

Recommended Work:	<input type="checkbox"/> Minor Rehab	<input type="checkbox"/> Major Rehab	Maintenance Needs:
	<input type="checkbox"/> Replace	<input checked="" type="checkbox"/> None	
Timeframe:	<input type="checkbox"/> Urgent	<input type="checkbox"/> 1 - 5 Years	<input type="checkbox"/> 6 - 10 Years
Comments:			

Element Photos



Comments:

Element Data

Element Group:	Deck	Length:	6.2	(m)		
Element Name:	Wearing Surface	Width:	7.8	(m)		
Location:	Deck	Height:	0.05	(m)		
Material:	Surface Treatment	Count:	2	each		
Element Type:	-	Total Quantity:	96.72	(m ²)		
Environment:	Benign / Moderate / Severe	Limited Insp'n:	<input type="checkbox"/>			
Protection System:	-					
Condition	Units	Exc.	Good	Fair	Poor	Performance Deficiencies
Data:	m ² / m / each / % / all		30	62.72	4	None

Comments: Raveling at the north and south edges of wearing surface. Moderate snowplow scrapes on surface and covered in gravel patches.

Performance Deficiencies:

Recommended Work:	<input type="checkbox"/> Minor Rehab	<input type="checkbox"/> Major Rehab	Maintenance Needs:
	<input type="checkbox"/> Replace	<input checked="" type="checkbox"/> None	
Timeframe:	<input type="checkbox"/> Urgent	<input type="checkbox"/> 1 - 5 Years	<input type="checkbox"/> 6 - 10 Years
Comments:	Remove gravel from wearing surface.		

Element Photos



Comments:

Municipal Structure Inspection Form
 Temagami Lake Access Road Bridge

MTO Site Number:

Element Data

Element Group:	Decks	Length:	6.15	(m)		
Element Name:	Soffit	Width:	6.6	(m)		
Location:	-	Height:	n/a	(m)		
Material:	Wood-Fibre Glass	Count:	n/a	each		
Element Type:	-	Total Quantity:	40.6	(m ²)		
Environment:	<u>Benign</u> / Moderate / Severe	Limited Insp'n:	<input type="checkbox"/>			
Protection System:	-					
Condition	Units	Exc.	Good	Fair	Poor	Performance Deficiencies
Data:	<u>m²</u> / m / each / % / all		40.6			None

Comments: Structural steel repainted.

Performance Deficiencies:

Recommended Work:	<input type="checkbox"/> Minor Rehab	<input type="checkbox"/> Major Rehab	Maintenance Needs:		
	<input type="checkbox"/> Replace	<input checked="" type="checkbox"/> None	<input type="checkbox"/> Urgent	<input type="checkbox"/> 1 Year	<input type="checkbox"/> 2 Year
Timeframe:	<input type="checkbox"/> Urgent	<input type="checkbox"/> 1 - 5 Years	<input type="checkbox"/> 6 - 10 Years		
Comments:					

Element Photos



Comments:

Municipal Structure Inspection Form
 Temagami Lake Access Road Bridge

MTO Site Number:

Element Data

Element Group:	Barriers	Length:	7.33	(m)		
Element Name:	Railing Systems	Width:	n/a	(m)		
Location:	North and South sides of Deck	Height:	0.74	(m)		
Material:	Steel	Count:	2	each side		
Element Type:	HSS 100x100	Total Quantity:	29.3	(m ²)		
Environment:	Benign / Moderate / Severe	Limited Insp'n:	<input type="checkbox"/>			
Protection System:	Steel Coating					
Condition	Units	Exc.	Good	Fair	Poor	Performance Deficiencies
Data:	m ² / m / each / % / all		28	1.3		

Comments: Light corrosion on HSS and minor scratches from snowplow.

Performance Deficiencies:

Recommended Work:	<input type="checkbox"/> Minor Rehab	<input type="checkbox"/> Major Rehab	Maintenance Needs:
	<input type="checkbox"/> Replace	<input checked="" type="checkbox"/> None	
Timeframe:	<input type="checkbox"/> Urgent	<input type="checkbox"/> 1 - 5 Years	<input type="checkbox"/> 6 - 10 Years
Comments:			

Element Photos



Comments:

Municipal Structure Inspection Form
 Temagami Lake Access Road Bridge

MTO Site Number:

Element Data

Element Group:	Barriers	Length:	0.2	(m)		
Element Name:	Posts	Width:	0.2	(m)		
Location:	North and South sides of Deck	Height:	0.77	(m)		
Material:	Steel	Count:	4	each side		
Element Type:	W Sections	Total Quantity:	8.0	each		
Environment:	Benign / Moderate / Severe	Limited Insp'n:	<input type="checkbox"/>			
Protection System:	Steel Coating					
Condition	Units	Exc.	Good	Fair	Poor	Performance Deficiencies
Data:	m ² / m each / % / all		8			

Comments: Steel barriers repainted. Light corrosion and light flaking on barrier base on road side.

Performance Deficiencies:

Recommended Work:	<input type="checkbox"/> Minor Rehab	<input type="checkbox"/> Major Rehab	Maintenance Needs:		
	<input type="checkbox"/> Replace	<input checked="" type="checkbox"/> None	<input type="checkbox"/> Urgent	<input type="checkbox"/> 1 Year	<input type="checkbox"/> 2 Year
Timeframe:	<input type="checkbox"/> Urgent	<input type="checkbox"/> 1 - 5 Years	<input type="checkbox"/> 6 - 10 Years		
Comments:					

Element Photos



Comments:

Municipal Structure Inspection Form
Temagami Lake Access Road Bridge

MTO Site Number:

Element Data

Element Group:	Approaches	Length:	15	(m)
Element Name:	Barrier	Width:	n/a	(m)
Location:	East and West Approaches	Height:	0.90	(m)
Material:	Steel	Count:	2	each side
Element Type:	Steel Beam Guid Rail	Total Quantity:	60.0	(m)
Environment:	Benign / Moderate / Severe	Limited Insp'n:	<input type="checkbox"/>	
Protection System:	Galvanized			Performance Deficiencies
Condition Data:	Units: m ² / m each / % / all	Exc.:	60	
		Good:		
		Fair:		
		Poor:		

Comments: Barrier replaced in 2022. Minor post damage at southeast corner (local).

Performance Deficiencies:

Recommended Work:	<input type="checkbox"/> Minor Rehab	<input type="checkbox"/> Major Rehab	Maintenance Needs:
	<input type="checkbox"/> Replace	<input checked="" type="checkbox"/> None	
Timeframe:	<input type="checkbox"/> Urgent	<input type="checkbox"/> 1 - 5 Years	<input type="checkbox"/> 6 - 10 Years
Comments:			

Element Photos



Comments:

Municipal Structure Inspection Form
Temagami Lake Access Road Bridge

MTO Site Number:

Element Data

Element Group:	Approaches	Length:	0.2	(m)		
Element Name:	Barrier Posts	Width:	0.2	(m)		
Location:	East and West Approaches	Height:	0.90	(m)		
Material:	Wood	Count:	2	each side		
Element Type:	Dimension Lumber	Total Quantity:	4	each		
Environment:	Benign / Moderate / Severe	Limited Insp'n:	<input type="checkbox"/>			
Protection System:	Treated					
Condition	Units	Exc.	Good	Fair	Poor	Performance Deficiencies
Data:	m ² / m each / % / all		4			

Comments: Light-moderate rotting and splitting in all posts

Performance Deficiencies:

Recommended Work:	<input type="checkbox"/> Minor Rehab	<input type="checkbox"/> Major Rehab	Maintenance Needs:		
	<input type="checkbox"/> Replace	<input checked="" type="checkbox"/> None	<input type="checkbox"/> Urgent	<input type="checkbox"/> 1 Year	<input type="checkbox"/> 2 Year
Timeframe:	<input type="checkbox"/> Urgent	<input type="checkbox"/> 1 - 5 Years	<input type="checkbox"/> 6 - 10 Years		
Comments:					

Element Photos



Comments:

Element Data

Element Group:	Approach	Length:	6	(m)		
Element Name:	Wearing Surface	Width:	7.8	(m)		
Location:	East and West Approaches	Height:	0.05	(m)		
Material:	Surface Treatment	Count:	2	each		
Element Type:	-	Total Quantity:	93.6	(m ²)		
Environment:	Benign / Moderate / Severe	Limited Insp'n:	<input type="checkbox"/>			
Protection System:	-					
Condition	Units	Exc.	Good	Fair	Poor	Performance Deficiencies
Data:	m ² / m / each / % / all		30	59.6	4	None

Comments: Gravel is covering majority of approaching wearing surface. Moderate scraps from snowplow. Low area at southwest corner (in poor condition).

Performance Deficiencies:

Recommended Work:	<input type="checkbox"/> Minor Rehab	<input type="checkbox"/> Major Rehab	Maintenance Needs:
	<input type="checkbox"/> Replace	<input checked="" type="checkbox"/> None	
Timeframe:	<input type="checkbox"/> Urgent	<input type="checkbox"/> 1 - 5 Years	<input type="checkbox"/> 6 - 10 Years
Comments:	Remove gravel from wearing surface.		

Element Photos



Comments:

Municipal Structure Inspection Form
Temagami Lake Access Road Bridge

MTO Site Number:

Element Data

Element Group:	Approaches	Length:	n/a	(m)		
Element Name:	Signage	Width:	n/a	(m)		
Location:	East and West Approaches	Height:	n/a	(m)		
Material:	-	Count:	2	each side		
Element Type:	-	Total Quantity:	4	each		
Environment:	Benign / Moderate / Severe	Limited Insp'n:	<input type="checkbox"/>			
Protection System:	-					
Condition	Units	Exc.	Good	Fair	Poor	Performance Deficiencies
Data:	m ² / m / each / % all	4				

Comments: 4 hazard signs replaced in 2022.

Performance Deficiencies:

Recommended Work:	<input type="checkbox"/> Minor Rehab <input type="checkbox"/> Major Rehab <input type="checkbox"/> Replace <input checked="" type="checkbox"/> None	Maintenance Needs:
Timeframe:	<input type="checkbox"/> Urgent <input type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years	<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Year
Comments:		

Element Photos

Comments:

Element Data

Element Group:	Embankments and Streams	Length:	n/a	(m)		
Element Name:	Streams and Waterways	Width:	n/a	(m)		
Location:	-	Height:	n/a	(m)		
Material:	-	Count:	1	each		
Element Type:	-	Total Quantity:	1	all		
Environment:	<u>Benign</u> / Moderate / Severe	Limited Insp'n:	<input type="checkbox"/>			
Protection System:	-					
Condition	Units	Exc.	Good	Fair	Poor	Performance Deficiencies
Data:	m ² / m / each / % <u>all</u>			1		

Comments: Remnants of beaver dam noted immediately upstream (south) of bridge.

Performance Deficiencies:

Recommended Work:	<input type="checkbox"/> Minor Rehab	<input type="checkbox"/> Major Rehab	Maintenance Needs:
	<input type="checkbox"/> Replace	<input checked="" type="checkbox"/> None	
Timeframe:	<input type="checkbox"/> Urgent	<input type="checkbox"/> 1 - 5 Years	<input type="checkbox"/> 6 - 10 Years
Comments:	Clear beaver dam upstream (south).		

Element Photos



Comments:

Element Data

Element Group:	Embankments and Streams			Length:	n/a	(m)
Element Name:	Slope Protection			Width:	n/a	(m)
Location:	Abutment Front and Side Slopes			Height:	n/a	(m)
Material:	Stone			Count:	2	each
Element Type:	Rip Rap			Total Quantity:	2	each
Environment:	Benign / Moderate / Severe			Limited Insp'n:	<input type="checkbox"/>	
Protection System:	-					Performance Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor	
	m ² / m / each / % / all	1		1		None
Comments: West gabions replaced in 2022. East gabions pulling from east abutment wall and undermining. Erosion at northeast quadrant.						
Performance Deficiencies:						
Recommended Work:	<input type="checkbox"/> Minor Rehab		<input checked="" type="checkbox"/> Major Rehab		Maintenance Needs:	
	<input type="checkbox"/> Replace		<input type="checkbox"/> None			
Timeframe:	<input type="checkbox"/> Urgent		<input checked="" type="checkbox"/> 1 - 5 Years		<input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Year	
Comments: Reinstall gabion baskets after undermining rehabilitation on east side.						

Element Photos



Comments: