

Sabrina Pandolfo

From:

Alimpic, Vesna (MECP) [REDACTED]

Good morning,

Attached to this email is the report for the recent announced inspection completed at Temagami North Drinking Water System at 5 Cedar Avenue South, Temagami on June 13, 2024 and the corresponding Incident Rating Report (IRR) and Risk Methodology document. This report provides an assessment of compliance and conformance based on observations and information available during the inspection review period only.

One instances of non-compliance was identified during the inspection. The operating authority took necessary steps to bring the system into compliance therefore there are no required actions to address this non-compliance. This non-compliance is described in the “*Non-compliance*” section within the report. Additional findings and applicable comments, where provided, will be found within the report.

The IRR is a summarized quantitative measure of the drinking water system’s annual inspections and is published in the Ministry’s Chief Drinking Water Inspector’s Annual Report. The Risk Methodology document describes the risk rating methodology which has been applied to the findings of the Ministry’s municipal residential drinking water system inspection results. Please find attached the corresponding IRR in Appendix A and Risk Methodology document.

Section 19 of the Safe Drinking Water Act (Standard of Care) creates a number of obligations for individuals who exercise decision-making authority over municipal drinking water systems. Please be aware that the Ministry has encouraged such individuals, particularly municipal councillors, to take steps to be better informed about the drinking water systems over which they have decision-making authority. These steps could include asking for a copy of this inspection report and a review of its findings. Further information about Section 19 can be found in “Taking Care of Your Drinking Water: A Guide for Members of Municipal Councils” on the Drinking Water Ontario website at <https://www.ontario.ca/environment-and-energy/taking-care-your-drinking-water-guide-members-municipal-councils>.

Attached in Appendix B is a document entitled “DWS Components Information” and in Appendix C is a document titled “Key Reference and Guidance Material for Municipal Residential Drinking Water Systems”.

Electronic copies of this inspection report have been sent to the Timiskaming Health Unit in accordance with the Ministry’s Municipal Drinking Water Inspection Protocol.

Thank you for your co-operation. If you have any questions about this inspection report, please contact me.

Kind regards,

Vesna Alimpic (she/her)
Water Compliance Officer
Provincial Officer Badge No. 1882
Timmins District
Drinking Water and Environmental Compliance Division

Ministry of the Environment, Conservation and Parks
191 Booth Road Unit 16 & 17
North Bay, ON P1A 4K3
Tel: 705 491-2781 Fax: 705 497-6866

We want to hear from you. How was my service? You can provide feedback at 1-888-745-8888 or ontario.ca/inspectionfeedback